

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31 only, T19-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 1 Page(s) 406)

Fir 12" dia., which I mark for cor. to secs. 30 & 31, T19S R8W S30 on NE.; T19S R8W S31 on SE. faces, with 5 notches on N. and 1 notch on S. edges; from which

A Fir 12" dia., bears N.66½°E., 26 lks. dist. mkd. T19S R8W S30 BT.

A Fir 18" dia., bears S.40½°E., 24 lks. dist. mkd. T19S R8W S31 BT.

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13017-18)

The cor. of secs. 30 & 31 only, marked by the remains of the original corner tree; a rotted Fir stump, 24" dia., from which the original bearing trees:

A Fir 16" dia., bears N.70°E., 26 lks. dist. with scribe marks 19S R8W S30 visible on opened and partly healed blaze. (Rec. brg. N.66½°E.)

A Fir 25" dia., bears S.40°E., 24 lks. dist., with a healed blaze. (Rec. brg. S.40½°E.)

At the corner point, through stump of corner tree, Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd: T 19 S T 19 S

S 36 | S 30
 | S 31
R 9 W R 8 W
1957

from which a new bearing tree:

A Fir 20" dia., bears N.4 3/4°E., 46 lks. dist. mkd. T19S R8W S30 BT.

Fd. OK, June 5, 1981 by L. Roberts - M 87-78

BLM dependent resurvey by Edith M Forkner & Jason A Lightbown, Cadastral Surveyors, under Group #2820, surveyed Feb./June 2016 - (DCSO records Vol. 59 Page(s) 23532-3)

The cor. of secs. 30 & 31 only, monumented with an iron post, 2" dia., firmly set, projecting 12" above ground, with a brass cap (properly) mkd.

from which the remains of the original bearing trees

A roothole bears N.70°E., 17.2 ft., alongside of which is a down fir, 13" dia., with illegible scribe marks visible on open blaze.

continued next page

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 700142

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31 only, T19-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A roothole bears S.40°E., 15.8 ft., alongside of which is a down fir, 24" dia., no marks visible.

and the remains of a BT mkd. by Tillman, et al. in 1957-58

A decayed fir stump, 14" dia., bears N.4¾°E., 30.4 ft., with a healed blaze.

and new bearing trees

A hemlock, 10" dia., bears N.27¾°E., 41.8 ft., mkd. T19S R8W S30 BT.

A hemlock, 11" dia., bears S.57¼°E., 30.3 ft., mkd. T19S R8W S31 BT.

There are trees to the E., S., and SW. with large blazes at waist height and cruiser's marks.

Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center & has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. angle iron driven alongside each corner.