

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 700302

PRIMARY CORNER DESCRIPTION W. 1/4 cor. for Sec. 19 only, T19-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 1 Page(s) 407)

-----  
Set post 4 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. marked ¼ S on W. face; dug pits, 18x18x12 ins., E. & W. of post, 5½ ft. dist.; and raised mound of earth, 1½ ft. high, 3½ ft. base, around post. No live trees in limits.

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13021)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd:

T 19 S  
¼ S 19  
R 8 W  
1957

from which

A Fir 24" dia., bears N.26½°E., 55 lks. dist. mkd. ¼ S19 BT.

An Alder 8" dia., bears S.37½°E., 13 lks. dist. mkd. ¼ S19 BT.

Cor. OK and tied in BLM survey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 - (DCSO records Vol.37 Page(s) 15434-35)

Cor. used in GLO resurvey by BLM John P. Farnsworth, Cadastral Surveyor, under Group #1076, surveyed Sept. 1981/April 1983 - (DCSO records Vol. 45 Page(s) 17468)