

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 700403

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 18 only, T19-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 1 Page(s) 408)

A Fir 14" dia., which I mark for ¼ sec. cor., ¼ S on W. face; from which

A Fir 14" dia., bears N.60°E., 36 lks. dist. mkd. ¼ S BT. No tree convenient on W. side; dug pits, 18x18x12 ins., 5½ ft. W. of post; and raised mound of earth, 3½ ft. base, 1½ ft. high, around post.

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13023-24)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd:

T 19 S
¼ S 18
R 8 W
1957

from which

A Fir 41" dia., bears N.77½°E., 41 lks. dist. mkd. ¼ S18 BT.

A Fir 30" dia., bears S.66°E., 19 lks. dist. mkd. ¼ S18 BT.

Cor. Fd. OK in BLM resurvey by John P. Farnsworth, Cadastral Surveyor, under Group #1076, surveyed Sept. 1981/April 1983 (DCSO records Vol. 45 Page(s) 17472)