

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18 only, T19-8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 1 Page(s) 408-09)

500 ft. above table land, Set post 4 ft. long, 4" sq., 24" in ground for cor. to secs. 7 & 18, mkd. T19S R8W S7 on NE.; T19S R8W S18 on SW. faces, with 2 notches on N. and 4 notches on S. edges; from which
A Fir 10" dia., bears N.44½°E., 48 lks. dist. mkd. T19S R8W S7 BT.
A Fir 10" dia., bears S.20°E., 42 lks. dist. mkd. T19S R8W S18 BT.

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13025)

The cor. of secs. 7 & 18, determined at record bearing and distance from the only remaining original bearing tree:
A broken Fir stump 25" dia., bears N.44½°E., 48 lks. dist., with scribe marks T19S R8W S7 visible on opened blaze, partly on stump and partly on fallen trunk.

At the corner point
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd:
T 19 S T 19 S
S 13 $\frac{S 7}{S 18}$
R 9 W R 8 W
1957

from which new bearing trees:
A Fir 22" dia., bears N.87 3/4°E., 63 lks. dist. mkd. T19S R8W S7 BT.
A Fir 23" dia., bears S.54¼°E., 61 lks. dist. mkd. T19S R8W S18 BT.