

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 31 & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 299)

The ¼ sec. cor., established on former survey*, which is a post, 3 ft. long, 3" sq., 24" in the ground, mkd: ¼ S31 on W and 32 on E faces; from which

A Fir, 6" dia., bears S.35°E., 30 lks., mkd: ¼ S BT.

A Fir, 9" dia., bears S.11°W., 14 lks., mkd: ¼ S BT.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM Resurvey by Peter A. Peterson; Glenn F. Goodson; John P. Lee, Cadastral Surveyors, under Group #948, surveyed Aug. 1978/Aug. 1979 - (DCSO records Vol. 41 Page(s) 16301)

Point for ¼ sec. cor. of secs. 31 & 32, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 20" in the ground, and in a mound of stone, 2½ ft. base, to top, with brass cap marked:

T19S R10W

¼

S 31 S 32

1979

from which

A Fir, 19" dia., bears S.61°E., 33 lks., mkd: ¼ S32 BT.

A Fir, 29" dia., bears N.66½°W., 49 lks., mkd: ¼ S31 BT.