

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, 30, 31, & 32

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 299)

The cor. of secs. 29, 30, 31, & 32, established on former survey*, which is a basalt stone, 16x10x4 ins. set 12" in the ground, mkd: with 1 notch on S & 5 notches on E edges; from which

- A Fir, 16" dia., bears N.31°E., 51 lks., mkd: T19S R10W S29 BT.
- A Fir, 20" dia., bears S.61°E., 18 lks., mkd: T19S R10W S32 BT.
- A Fir, 20" dia., bears S.44°W., 40 lks., mkd: T19S R10W S31 BT.
- A Fir, 15" dia., bears N.10°W., 51 lks., mkd: T19S R10W S30 BT.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM Resurvey by Peter A. Peterson; Glenn F. Goodson; John P. Lee, Cadastral Surveyors, under Group #948, surveyed Aug. 1978/Aug. 1979 - (DCSO records Vol. 41 Page(s) 16302)

The corner of secs. 29, 30, 31, & 32, determined from the remains of the orig. BTs:

- A Fir, 45" dia., bears S.65½°E., 18 lks., with healed blaze. (Rec. S.61°E.)
- A Fir snag, 25" dia., bears S.44°W., 40 lks., with scribe marks R S T visible on opened blaze.
- A Fir, 28" dia., bears N.5°W., 47 lks., with healed blaze. (Rec. N.10°W., 51 lks.)

At the corner point

Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

T19S R10W
S 30 S 29
S 31 S 32
1978

from which new BTs:

- A Fir, 36" dia., bears N.28½°E., 66 lks., mkd: T19S R10W S29 BT.
- A Fir, 18" dia., bears S.52½°W., 80 lks., mkd: T19S R10W S31 BT.