TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 296)

The ¼ sec. cor., established by me on former survey*, which is a post, 3 ft. long, 3" sq., set 24" in the ground, mkd: ¼ S29 on W and 28 on E faces; from which

A Fir, 4" dia., bears N.11°W., 11 lks., mkd: ¼ S BT.
A Fir, 6" dia., bears S.20°E., 13 lks., mkd: ¼ S BT.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

Ernest Alvarado, USFS & Dep. Douglas Co. Surveyor - Carol Dickison - 11/2/1978 - C.S. File 60/17-21

Not found.
No evidence of ¼ corner between secs. 28 & 29, T19S R10W was found, ran a compass line and measure the distance from the section corner the area of the ¼ corner. Two GLO notes calls between the corner match and ravine after leaving the area north.
No evidence of BTs or other accessories found.

BLM dependent resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/Oct. 1989 - (DCSO records Vol. 49 Page(s) 18790-91)

Point for ¼ sec. cor. of secs. 28 & 29, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T19S R10W
¼
S 29 | S 28
1989

from which

A Fir, 30" dia., bears S.34¾°E., 102½ lks., mkd: ¼ S28 BT.
A Fir, 13" dia., bears S.54¼°W., 77½ lks., mkd: ¼ S29 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.