

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 290)

The ¼ sec. cor., established on former survey*, which is a Fir post, 3 ft. long, 3" sq., 24" in the ground, mkd: ¼ S28 on W and 27 on E faces; from which

An Alder, 6" dia., bears N.5°E., 7 lks., mkd: ¼ S BT.

An Alder, 7" dia., bears S.7°W., 10 lks., mkd: ¼ S BT.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

Ernest Alvarado, USFS & Dep. Douglas Co. Surveyor - Carol Dickison - 12/8/1978 - C.S. File 60/17-30

Not found.

No evidence of ¼ corner between secs. 27 & 28, T19S R10W was found, the bearing and distance fell in old clearcut and the area has all slide down to the creek. GLO notes calls fit the area.

No evidence of BTs or other accessories found.

BLM dependent resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/Oct. 1989 - (DCSO records Vol. 49 Page(s) 18787)

Point for ¼ sec. cor. of secs. 27 & 28, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 23" in the ground, with brass cap mkd:

T19S R10W
¼
S 28 | S 27
1989

from which

A Fir, 11" dia., bears S.73°E., 31 lks., mkd: ¼ S27 BT.

A Fir, 8" dia., bears S.62 ¾°W., 23½ lks., mkd: ¼ S28 BT
Deposit white "DEEP-1" magnetic marker at base of stainless steel post.