

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Cor. Secs. 21, 22, 27, & 28

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 291)

-----  
Set a sandstone, 12x8x7 ins., 8" in the ground, for cor. of secs. 21, 22, 27, & 28, marked with 2 notches on S & 3 notches on E edges; and raised a mound of stone, 2 ft. base, 1½ ft., high, W of cor. Pits impracticable. No trees within limits.

Old cor. bears West 5 lks., I destroy it.

\* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/Oct. 1989 - (DCSO records Vol. 49 Page(s) 18787)

-----  
Point for cor. of secs. 21, 22, 27, & 28, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 18" in the ground, with brass cap mkd:

T19S R10W  
S 21 | S 22  
S 28 | S 27  
1989

from which

A Fir, 21" dia., bears N.79½°E., 92 lks., mkd: T19S R10W  
S22 BT.

A Fir, 30" dia., bears S.80°E., 90½ lks., mkd: T19S R10W  
S27 BT.

A Fir, 32" dia., bears S.70°W., 36 lks., mkd: T19S R10W  
S28 BT.

A Fir, 38" dia., bears N.46°W., 3½ lks., mkd: T19S R10W  
S21 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Corner is located on a SE slope in timber.