

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 291)

The old ¼ sec. cor. established on former survey*, which is a Fir post, 3 ft. long, 3" sq., 24" in the ground, mkd: ¼ S22 on N and 27 on S faces; from which

A Fir, 6" dia., bears N.15°E., 12 lks., mkd: ¼ S BT.

A Fir, 7" dia., bears S.20°W., 11 lks., mkd: ¼ S BT.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/Oct. 1989 - (DCSO records Vol. 49 Page(s) 18788)

Point for ¼ sec. cor. of secs. 22 & 27, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 18" in the ground, with brass cap mkd:

T19S R10W
 S 22
¼ S 27
1989

from which

A Cedar, 16" dia., bears S.34¼°E., 82 lks., mkd: ¼ S27 BT.

A Fir, 49" dia., bears N.46°W., 78½ lks., mkd: ¼ S22 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

From this point, the USFS GPS station #191022, bears N.32°14'30"W., 17.833 chs., monumented with an alum. post, 2½" dia., firmly set flush with ground surface, with alum. cap mkd: GPS 191022 + 1988.