

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 284)

-----  
Set a Fir post, 3 ft. long, 4" sq., 24" in the ground, for cor. of secs. 22, 23, 26, & 27, mkd: T19S S23 on NE, R10W S26 on SE, S27 on SW and S 22 on NW faces, with 2 notches on S & E edges; from which

- A Fir, 4" dia., bears N.10°E., 15 lks., mkd: T19S R10W S23 BT.
- A Fir, 4" dia., bears S.25°E., 10 lks., mkd: T19S R10W S26 BT.
- A Fir, 5" dia., bears S.50°W., 26 lks., mkd: T19S R10W S27 BT.
- A Fir, 6" dia., bears N.8°W., 20 lks., mkd: T19S R10W S22 BT.

Old cor. bears East 7 lks., I destroy it.  
\* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/Oct. 1989 - (DCSO records Vol. 49 Page(s) 18783)

-----  
Point for cor. of secs. 22, 23, 26 & 27, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 23" in the ground, with brass cap marked:

T19S R10W  
S 22 S 23  
S 27 S 26  
1989

- from which
- A Cedar, 16" dia., bears N.18°E., 125 lks., mkd: T19S R10W S23 BT.
  - A Cedar, 18" dia., bears S.55°E., 34½ lks., mkd: T19S R10W S26 BT.
  - A Hemlock, 32" dia., bears S.44½°W., 45 lks., mkd: T19S R10W S27 BT.
  - A Hemlock, 23" dia., bears N.65 3/4°W., 130 lks., mkd: T19S R10W S22 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.