TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 277)

Set an Alder post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S23 on W and 24 on E faces; from which
An Alder, 6" dia., bears N.10°E., 14 lks., mkd: ¼ S BT.
A Fir, 8" dia., bears S.4°W., 20 lks., mkd: ¼ S BT.
Old cor. bears S.70°E., 10 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/Oct. 1989 - (DCSO records Vol. 49 Page(s) 18773)

Point for ¼ sec. cor. of secs. 23 & 24, at proportionate distance; there is no remaining evidence of the orig. corner. Set an stainless steel, 28" long, 2½" dia., 23" in the ground, with brass cap marked:
T19S R10W
¼
S 23 S 24
1989
from which
A Fir, 46" dia., bears N.74½°E., 21 lks., mkd: ¼ S24 BT.
A Cedar, 14" dia., bears N.38 3/4°W., 36½ lks., mkd: ¼ S23 BT.
Deposit white "DEEP-1" magnetic marker at base of stainless steel post.