

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 275)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S25 on N and 36 on S faces; from which
A Fir, 7" dia., bears N.11°E., 11 lks., mkd: ¼ S BT.
A Fir, 8" dia., bears S.10°E., 17 lks., mkd: ¼ S BT.
Old cor. bears North 2 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

James W. Prochnau - For: US Forest Service - July 29, 1971 - C.S. File 55/206-5 - M 43-22

No evidence found of the orig. corner. At the properly proportioned dist., I placed 2"x36" galv. iron pipe, flanged at the bottom & capped with a bronze disk, monument projects 6" above the ground, filled in around the pipe monument w/stone & packed earth. I stamped the disk:

¼ S 25
 S 36
 1971
 4185

I established new BTs as follows. Each BT has a scribed face & a USFS BT sign breast high & facing the monument:
A 32" D.Fir bears N.10°E., 50.3 ft.
A 28" D.Fir bears S.60°E., 29.27 ft.

Fd. Ok by E. Alvarado, USFS, 3/28/1980 - C.S. File 61/6-18