TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 277)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S24 on N and 25 on S faces; from which
A Fir, 4" dia., bears N.7°E., 15 lks., mkd: ¼ S BT.
A Fir, 5" dia., bears S.8°E., 20 lks., mkd: ¼ S BT.
Old cor. bears South 5 lks., I destroy it.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/Oct. 1989 - (DCSO records Vol. 49 Page(s) 18771-72)

Point for ¼ sec. cor. of secs. 24 & 25, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T19S R10W
¼ S 24
S 25
1989

from which
A Fir, 43" dia., bears S.58°W., 37 lks., mkd: ¼ S25 BT.
A Cedar, 25" dia., bears N.2°W., 38 lks., mkd: ¼ S24 BT.
Deposit white "DEEP-1" magnetic marker at base of stainless steel post.