

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 278)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ secs. cor. mkd: ¼ S13 on N and 24 on S faces; from which
 A Fir, 6" dia., bears N.30°E., 10 lks., mkd: ¼ S BT.
 A Fir, 4" dia., bears S.25°W., 12 lks., mkd: ¼ S BT.
 Old cor. bears South 7 lks., I destroy it.
 * 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

Douglas Co. Surveyors Office - John Powell - Feb. 1971 - C.S. File 53/66-45

Reported as not found
 Found approx. location - US tag on tree 56" D.Fir S.60°W., 60.0' to approx. corner. USFS has no idea how it got there.

BLM dependent resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/Oct. 1989 - (DCSO records Vol. 49 Page(s) 18776)

Point for ¼ sec. cor. of secs. 13 & 24, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

	T19S	R10W
	¼	<u>S 13</u>
		S 24
	1989	

from which
 A Fir, 13" dia., bears S.31¼°W., 53½ lks., mkd: ¼ S24 BT.
 A Fir, 9" dia., bears N.12°W., 20½ lks., mkd: ¼ S13 BT.
 Deposit white "DEEP-1" magnetic marker at base of stainless steel post.
 From this point, a point established as an approx. ¼ sec. cor. of secs. 13 & 24 by C.E. Worthylake etal, employees of Davidson Indust., in 1968, bears S.77°52'W., 1.312 chs., determined from the BTs mkd. by Worthylake:
 A Cedar stump, 48" dia., bears N.77°E., 58 lks., no scribe marks on unhealed blaze.
 A Fir, 18" dia., at base of old growth Fir, 6 ft. dia., bears N.65°W., 80 lks., with healed blaze.