

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 700211

PRIMARY CORNER DESCRIPTION C C for Secs. 30 & 31 only, T19-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 411)

At point of intersection (9.16 chs. N. of cor. of secs. 25 & 36) A Fir 20" dia. for closing cor. of secs. 30 & 31, I mark CC T19S R9W on E.; S31 on S. and S30 on N. sides, with 1 notch on S. and 5 notches on N. sides; from which
An Alder 14" dia., bears N.10°E., 8 lks. dist. mkd. T19S R9W S30 BT.
A Cherry 15" dia., bears S.29½°E., 30 lks. dist. mkd. T19S R9W S31 BT.

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 19, 1899 - (DCSO records Vol. 1 Page(s) 270)

The old closing cor. to secs. 30 & 31, T19-10 which I destroy. * 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13029-30)

Point for the closing corner of ses. 30 and 31, T19S R9W, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post 28" long, 2½" dia., 22" in the ground with brass cap mkd:

T 19 S T 19 S
S 25 S 30 CC
S 31
R 10 W R 9 W
1958

from which

A Hemlock 15" dia., bears N.24½°E., 57 lks. dist. mkd. T19S R9W S30 CC BT.

A Hemlock 40" dia., bears S.9°E., 37½ lks. dist. mkd. T19S R9W S31 CC BT.

Fd. OK and used in BLM survey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 - (DCSO records Vol. 37 Page(s) 15426)

(Cont. Next Page)

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 700211

PRIMARY CORNER DESCRIPTION C C for Secs. 30 & 31 only, T19-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/May 1991 - (DCSO records Vol. 49 Page(s) 18752)

(9.100 chs.)

The original closing cor. of secs. 30 & 31, monumented with the remains of the original corner tree, a Fir snag stump, 30" dia., with flattened pitch seams visible on top, in 20" core dia., facing N., E., and S., bears West, 0.725 chs. dist. Lying alongside is the log, sawed off end and uncovered scribe marks 9W on what was the E. side.

At the corner point

Drive an iron rod, 24" long, 5/8" dia., 20" into the top center of the corner stump, with alum. cap mkd:

	T19S	
R10W	R9W	
S 25	S 30	CC
	S 31	

1991
BLM

from which

A Cedar 35" dia., bears N.47¼°E., 160 lks. dist. mkd. T19S R9W S30 CC BT.

(10.725 chs.) (N.4°16'00"E.)

From this point, the closing cor. of secs. 30 and 31, T19S R9W, erroneously reestablished by Tillman, etal, in 1957-58, bears East, 0.060 chs. dist., monumented with an iron post 2½" dia., firmly set, projecting 4" above ground, with brass cap mkd. and witnessed as described in the official record. Remove the iron post and obliterate the scribe marks on the bearing trees.