

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 700311

PRIMARY CORNER DESCRIPTION C C for Secs. 19 & 30 only, T19-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 412)

At point of intersection (9.24 chs. N. of the cor. of secs. 24 & 25)
Set an Alder Post 3 ft. long, 4" sq., 24" in the ground, for closing cor. of secs. 19 & 30, mkd. T19S R9W CC on E.; S30 on S.; and S19 on N. faces, from which
 An Alder 5" dia., bears N.19°E., 29 lks. dist. mkd. T19S R9W S19 BT.
 An Alder 6" dia., bears S.70°E., 25 lks. dist. mkd. T19S R9W S30 BT.

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 19, 1899 - (DCSO records Vol. 1 Page(s) 271)

The old closing cor. of secs. 19 & 30, T19S R9W.: I destroy this cor.
* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13031)

Point for the closing corner of secs. 19 & 30, T19S R9W, at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post 28" long, 2½" dia., 22" in the ground, with brass cap mkd:
 T 19 S T 19 S
 S 24 $\frac{S 19}{S 30}$ CC
 R 10 W R 9 W
 1958
from which
 A Fir 38" dia., bears N.45°E., 98 lks. dist., mkd. T19S R9W S19 CC BT.
 A Fir 11" dia., bears S.55°E., 71 lks. dist. mkd. T19S R9W S30 CC BT.

Cor. Fd. OK and used in BLM survey by Donald R. Beck & Peter A. Peterson, Cadastral Surveyors, under Group #307, surveyed April 1968/Aug. 1976 - (DCSO records Vol. 37 Page(s) 15428)

(Cont. Next Page)

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 700311

PRIMARY CORNER DESCRIPTION C.C. for Secs. 19 & 30 only, T19-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/Oct. 1989 - (DCSO records Vol. 49 Page(s) 18767)

The closing cor. of secs. 19 & 30, monumented with an iron post 2½" dia., firmly set, projecting 2" above ground with brass cap mkd. in 1958,

from which the bearing trees mkd. by Tillman, etal

A Fir 43" dia., bears N.46 3/4°E., 98 lks. dist. with healed blaze. (Rec. N.45°E.)

A Fir 25" dia., bears S.61°E., 71 lks. dist. with healed blaze. (Rec. S.55°E.)