

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 18 only, T19-9

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13034)

Point for the ¼ sec. cor. of sec. 18 only, on the W. bdy. of T19S R9W, at midpoint between closing corners.

Set an iron post 28" long, 2½" dia., 22" in the ground with brass cap mkd:

¼
T 19 S
S 18
R 9 W
1958

from which

A Fir 38" dia., bears N.70°E., 9½ lks. dist. mkd. ¼ S18 BT.

A Fir 41" dia., bears S.60°E., 43 lks. dist. mkd. ¼ S18 BT.

BLM Resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/Oct. 1989 - (DCSO records Vol. 49 Page(s) 18770-71)

The ¼ sec. cor., monumented with an iron post 2½" dia., firmly set in a mound of stone, 4 ft. base, 2 ft. high, with brass cap mkd. in 1958,

from which the remains of bearing trees mkd. by Tillman, etal

A root hole bears N.70°E., 9½ lks. dist.

A Fir stump 50" dia., 1 ft. high, bears S.60°E., 43 lks. dist., no marks visible.

and new accessories:

A Fir 10" dia., bears N.37°E., 41½ lks. dist., mkd. ¼ S18 BT.

A stainless steel post 28" long, 2½" dia., set 28" in the ground for a reference monument, bears N.83°16'E., 79.5 lks. dist., with brass cap mkd. RM ¼ S18 52.5 FT TO COR 1989 and an arrow pointing to the corner.

Fd. OK, June 1991 by R. Ward - M 113-37 A & B