

PRIMARY CORNER DESCRIPTION Sec. Cor. for 12 & 13 only (East)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705, dated April 19, 1899 - (DCSO records Vol. 1 Page(s) 272)

Set a sandstone 20x6x5 ins., 15" in the ground, for cor. of secs. 12 & 13, marked with 4 notches on S. & 2 notches on N. edges; from which

 An Alder 4" dia., bears N.5°W., 28 lks. dist. mkd. T19S R10W S12 BT.

 A Fir 6" dia., bears S.63°W., 73 lks. dist. mkd. T19S R10W S13 BT.

From this cor. old cor. bears S.80°W., 15 lks. dist.; I destroy it.

(* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.)

BLM survey by Thomas A. Tillman; Robert L. Holm & Floyd A. Brooks, Cadastral Surveyors, under Group #307, surveyed May 1957/Sept. 1958 - (DCSO records Vol. 31 Page(s) 13035)

The cor. of secs. 12 & 13 only, monumented with a sandstone 20x6x5 ins., firmly set 10" in the ground, with 4 notches on S., and 2 notches on N. edges; from which the original bearing trees:

 A Fir 28" dia., bears S.66½°W., 68 lks. dist. plainly blazed and healed. (Rec. S.63°W., 73 lks. dist.)

 An Alder stump 12" dia., bears N.9°W., 31 lks. dist. with no marks remaining. (Rec. N.5°W., 28 lks. dist.)

At the corner point

Set an iron post 28" long, 2½" dia., 22" in the ground, with brass cap mkd.

 T 19 S

S 12

 S 13 S 18

 R 10 W R 9 W

 1958

from which a new bearing tree:

 A Fir 17" dia., bears N.26°W., 46 lks. dist. mkd. T19S R10W S12 BT.

Deposit the original stone alongside the base of the iron post.

Fd. OK, Sept. 1988 by D. Baker - M 107-1

Cor. Fd. OK and used in BLM Resurvey by Robert W. Dahl, Cadastral Surveyor, under Group #1450, surveyed Aug. 1988/May 1991 - (DCSO records Vol. 49 Page(s) 18753-54)

