

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by J.H. McClung under Contract #173 dated July 20, 1872 - (DCSO rec. Vol. 2 Page(s) 688

Set ¼ sec. cor. post; from which
A Fir, 11" dia., bears N.70°W., 13 lks.
A Fir, 17" dia., bears S.12°E., 25 lks.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; C Putnam, crew - Jan. 1962 - C.S. File 49/89-20

Found - Fir, now N.80°W., (instead of N.70°W.) 8.6 ft. Tree previously opened, scribing visible on old face "¼S". Tree still alive & in good condition.
Fir snag, now 19" S.12°E., 16.5 ft. chopped open & fd. good scribing on old face "S" & "BT" visible.
Set - Brass cap at corner mkd: County Surveyors Office 1962
T20S R6W ¼ S30|S29
17" D.Fir S.62°E., 31.0 ft., mkd: ¼ S29 CS BT
Note - ½" alum. pipe apparently set for this corner bears S.23°W., 3.8 ft.

Donald Peel - For: Weyerhaeuser - June 25, 1991 - M 113-45

Found - 1¼" iron pipe with DCSO brass cap dated 1962
12" Fir stump S.61°E., 30.6 ft. scribe visible.
18" Fir snag S.9½°E., 16.1 ft. scribe visible.
17" Fir N.82¼°W., 8.9 ft. closed face BLM tag.
22" Fir N.23½°W., 7.2 ft. Weyco & GLO tags. BT not of rec.