

PRIMARY CORNER DESCRIPTION Cor Secs 19, 20, 29, & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by J.H. McClung under Contract #173 dated July 20, 1872 - (DCSO rec. Vol. 2 Page(s) 688)

Set post for cor. to secs. 19, 20, 29, & 30; from which

- A Fir, 9" dia., bears N.80°W., 20 lks.
- A Fir, 22" dia., bears N.20°E., 45 lks.
- A Fir, 10" dia., bears S.18°W., 24 lks.
- A Fir, 18" dia., bears S.70°E., 55 lks.

A.H. Hinkson, July 3, 1937 (Rec'd from Lane Co. Surveyor's Office Feb. 20, 1962) C.S. File 53/1-1 & 52/104-1

Found - BTs in secs. 20 & 30 as described in the gov't notes but the ones in secs. 19 & 29 were down & rotted so I mkd:

- 30" R.Fir bearing N.48°W., 41 lks. T20S R6W S19 BT.
- 48" R.Fir bearing S.44°E., 66 lks. T20S R6W S29 BT.

There were no signs of a post left so I set a 4" dogwood post mkd: S19, 20, 29 & 30 according to the notes on the 2 BTs left standing.

Douglas Co. Surveyors Office - Milo Godfrey - Vernon Tracy - Clete Putnam - Feb. 8, 1962 - C.S. File 52/104-2

Found - ½" alum. pipe & squared, scribed stake.

- 44" Fir S.41°E., 43.5 ft., scribing visible on badly burned face "20S R6W S29" (blazed 15-20 yrs ago)
- 36" Fir N.52°W., 28.7 ft. some scribing visible on badly burned face "BT"
- 20" Fir snag N.18°E., 23.5 ft. scribing "T2 R6 0 BT"
- 14" Fir snag S.38°W., 21.8 ft. scribing "T20S R6W S30 BT BT"

None of this is orig. scribing no trace of any orig. BTs fd. Location questionable. Position of old stumps in immediate vicinity are closer than orig. trees.

Remonumentation of corner by Peter A. Peterson, Cadastral Surveyor, under Group #350, Sept. 1972 - (DCSO records Vol. 39 Page(s) 15708-9)

The cor. of secs. 19, 20, 29, & 30, determined at the record dist. from the remains of the orig. BTs:

- A Fir snag, 20" dia., bears N.20°E., 45 lks., with scribe marks BT visible on opened & decayed blaze.
- A decayed Fir stump, 14" dia., bears S.44°W., 26 lks., with scribe marks BT visible on opened blaze. (Rec. S.18°W.)

continued next page

Alias	Description
Alias	Description
Alias	Description
Alias	Description

and bearing trees mkd. & recorded by A.H. Hinkson, Dep. County Surveyor, in 1937

A Fir, 52" dia., bears S.47°E., 61 lks., with fragmentary scribe marks visible on opened & burned blaze.

A fir, 40" dia., bears N.41°W., 45 lks., with fragmentary scribe marks visible on partially open blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap mkd:

T 20	S	R 6	W
S 19		S 20	
S 30		S 29	
1972			

from the new BTs

A Fir, 24" dia. bears N.57°E., 33 lks mkd: T20S R6W S20 BT

A Fir, 8" dia. bears S.19°W., 38 lks mkd: T20S R6W S30 BT

Fd. BC & 6 BTs, by D. Peel, 6/1991, M113-45

Kent Inman - 9/8/2010 - C.S. File 65/69-63

Found - ¾" Brass cap, on a 2½" iron pipe, up 4". Found a metal U post 0.4' NW and a thin walled iron pipe 5.6' NE. (BLM 1972)

27" D.Fir, with a healed face and BLM BT tag, bears N.57°E., 21.6' (21.6' Baker visitation 1999) (33 links) (BLM1972)

46" D.Fir snag, 20± tall, with a BLM BT tag, and a healed face, also a cruisers mark bears S.47°E., 41.4' (41.4' Baker visitation 1999) (61 links BLM) (Hinkson, Lane County RE 850)

14" D.Fir stump, 4' tall, sniped, with a healed face and BLM BT tag bears S.19°W., 25.1' (BLM 1972)

37" D.Fir with a healed face and BLM BT tag, and a cruisers mark, bears N.41°W., 30.7' (45 links - BLM notes, 41 links on BLM 8.1. tag) (30.7 Baker visitation 1999) (Hinkson, Lane County RE 850)

New - 8" D.Fir, bears S.42°E., 20.3', scribed "T20S R6W S29 BT" a R.R.C. BT. tag was attached.

Comments - All faces were painted red, as was a 6' band around the trees & stump. The top of the stump was also painted red, Distances to the accessories were measured with a 75' Buckers Tape or a total station to the side center. Bearings were obtained or compared to those of record using Hand compass with the a declination set at 16°E.