

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Cor. Secs. 23, 24, 25, & 26

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by J.H. McClung under Contract #173 dated July 20, 1872 - (DCSO rec. Vol. 2 Page(s) 682

-----  
Set sandstone, 16x10x6, for cor. to secs. 23, 24, 25, & 26; from which  
A Laurel, 6" dia., bears S.70°W., 10 lks.

Douglas Co. Surveyors Office - Milo Godfrey - Feb. 1962 - C.S. File 49/89-38

-----  
Reported as searched for & not found.

BLM dependent resurvey by William W. Glenn, Cadastral Surveyor under Group #441 dated May 1962, surveyed June/July 1962 - (DCSO records Vol. 27 Page(s) 11324 A&B)

-----  
Point for the cor. of secs. 23, 24, 25 & 26, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 26" in the ground, with brass cap marked:

T 20 S R 6 W  
S 23 | S 24  
S 26 | S 25  
1962

from which

- A Fir, 23" dia. bears N.48½°E. 8 lks. mkd: T20S R6W S24 BT
- A Fir, 23" dia., bears S.70½°E., 41 lks., mkd: T20S R6W S25 BT.
- A Fir, 28" dia., bears S.72¾°W., 21½ lks., mkd: T20S R6W S26 BT.
- A Fir, 23" dia., bears N.30½°W., 30½ lks., mkd: T20S R6W S23 BT.

The cor. is located in the head of a ravine, drains S.70°W.

BLM dependant resurvey by Daniel N. Patterson & Craig Wanless, Cadastral Surveyors, Under group #1764 dated Jan. 1995, surveyed Jan./May 1995 - (DCSO records Vol. 52 Page(s) 19700)

-----  
Point for the cor. of secs. 23, 24, 25 & 26, at proportionate distance; there is no remaining evidence of the original corner.

Set a stainless steel post, 28" long, 2½" diam., 24" in the ground, with brass cap mkd.

T 20 S R 6 W  
S 23 | S 24  
S 26 | S 25  
1995

continued next page

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Cor. Secs. 23, 24, 25, & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which new bearing trees

A fir, 20" diam., bears N.29½°E., 23½ lks., mkd. T20S R6W S24 BT.

A chinquapin, 11" diam., bears S.35°E., 91 lks., mkd. T20S R6W S25 BT.

A fir, 21" diam., bears S.50°W., 19½ lks., mkd. T20S R6W S26 BT.

A fir, 31" diam., bears N.28¾° W., 109½ lks., mkd. T20S R6W S23 BT.

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

From this point, the cor. of secs. 23, 24, 25 & 26, erroneously reestablished by Glenn in 1962, bears S.1°47'W., 0.193 chs.; monumented with an iron post, 2½" diam., firmly set, projecting 2" above ground, with brass cap mkd. and witnessed as described in the official record. Remove the marks from the 1962 brass cap and remark the brass cap AM 12.74 FT 1995 and an arrow pointing toward the corner, no marks were removed from the bearing trees due to the size and condition of them.