

PRIMARY CORNER DESCRIPTION NE. Cor. S. 1, T20-8; SE. Cor S36, T19-8

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #486, dated August 1, 1883 (DCSO records Vol. 1 Page(s) 459-60)

Set post 6" dia., 4 ft. long, 12" in ground, with marked stone, for closing cor. to Town. 19 & 20 S., R 8 West, with 6 notches on each edge; from which
Fir 8" dia., bears N.38°E., 17 lks. dist. mkd. T20S R7W S6 BT.
Fir 8" dia., bears S.32°W., 5 lks. dist. mkd. T20S R8W S1 BT.
Fir 4" dia., bears N.27°W., 22 lks. dist. mkd. T19S R8W S36 BT.

GLO survey by C.M. Collier, Deputy Surveyor, under Contract #580, dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 498-99)

At the NE corner of T20S R8W, where found the post almost entirely burned. Set new post 4½ ft. long, 4" sq., 24" in ground, marked T20S R8W S1 on SW. and T19S R8W S36 on NW. faces, with 6 notches on N., W., and S. edges, from which
A Fir 8" dia., bears N.38°E., 17 lks. dist. mkd. T20S R7W S6 BT.
A Fir 8" dia., bears S.32°W., 5 lks. dist. mkd. T20S R8W S1 BT.
A Fir 4" dia., bears N.27°W., 22 lks. dist., mkd. T19S R8W S36 BT.

Fd. Cor. OK, with new post & 3 BTs. in GLO Survey by Thos. Todd, under Contract #574, dated May 19, 1891 - (DCSO records Vol. 2 Page(s) 567)

BLM Resurvey by Norman Price and Thomas Tillman, Cadastral Surveyors, under Group #284, Surveyed July 1947/Sept. 1948 - (DCSO records Vol. 31 Page(s) 12950)

The cor. of Tps. 19 & 20 S., R 8 W., is monumented with a shattered sandstone, 16x12x12 ins., firmly set, with incomplete chisel marks, located at the intersection of original blazed lines; the original bearing trees have been consumed by fire.
At the corner point
Set an iron post, 3 ft. long, 3" dia., 28" in the ground, with brass cap mkd: (Cont. Next Page)

TOWNSHIP 20 RANGE 07 POINT IDENTIFIER # 100662

PRIMARY CORNER DESCRIPTION NE. Cor. S. 1 T20-8; SE Cor. S. 36, T19-8

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

T 19 S
R 8 W T 20 S
S 36 R 7 W
S 1 S 6
T 20 S
1949

from which new bearing trees

A Fir 10" dia., bears N.2¼°W., 30 lks. dist. mkd. T19S R8W S36 BT.

A Fir 8" dia., bears S.85°W., 24 lks. dist. mkd. T20S R8W S1 BT.

BLM Remonumentation of corner by Wm. Glenn; C. Albert White and James E. Jelley, Cadastral Surveyors, under Group #'s 350 and 635, surveyed April/May 1967 - (DCSO records Vol. 43 Page(s) 16702-03)

(Corner report only)

The cor. of Tps. 19 & 20 S., R8W, monumented with an iron post 3" dia., firmly set, projecting 10" above ground, with brass cap mkd. in 1949,

from which bearing trees mkd. in 1949:

A Fir 13" dia., bears S.85°W., 24 lks. dist., with healed blaze.

A Fir 12" dia., bears N.2¼°W., 30 lks. dist., with healed blaze.

BLM Resurvey by Harvey E. Wofford & Lester E. Fischer, Cadastral Surveyors, under Group #913, Surveyed Aug. 1976/Aug. 1978 - (DCSO records Vol. 40 Page(s) 16091)

The cor. of Tps. 19 & 20 S., R8W., monumented with an iron post 3" dia., firmly set, projecting 12" above ground with brass cap mkd in 1949,

from which bearing trees mkd. by Price & Tillman:

A Fir 15" dia., bears N.2¼°W., 30 lks. dist., with healed blaze.

A Fir 17" dia., bears S.85°W., 24 lks. dist., with healed blaze.

Set a 5 ft. steel fence post alongside iron post.