

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 31 only, T19-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Thos. Todd, under Contract #574, dated May 19, 1891 - (DCSO records Vol. 2 Page(s) 567)

Set a Cedar post 4 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. marked ¼ S on N. face; from which
A Fir 20" dia., bears S.28°E., 28 lks. dist. mkd. ¼ S BT.
A Fir 36" dia., bears N.30°W., 14 lks. dist. mkd. ¼ S BT.

BLM Resurvey by Norman Price and Thomas Tillman, Cadastral Engineers, under Group #284, Surveyed June/Sept. 1949 - (DCSO records Vol. 31 Page(s) 13010-11 (Dup. Pg. 12949))

The ¼ sec. cor., determined at the record bearing from the original SE. bearing tree and at the record bearing and distance from the original NW. bearing tree, as follows:

- A Fir 24" dia., bears S.28°E., 18 lks. dist., plainly blazed and healed. (Rec. dist., 28 lks.)
- A Fir 50" dia., bears N.30°W., 14 lks. dist., plainly blazed and healed.

At the corner point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd: ¼ S 31
1949

from which a new bearing tree:

- A Fir 32" dia., bears N.29½°E., 53 lks. dist., marked ¼ S31 BT.

Robert J. Walters - For: U.S. Dept. of Interior - Oct. 4, 1974 - C.S. File 58/11

Found - 1949 Brass cap.

- D.Fir stump 32", 4.6 ft. high, bears N.30°W., 9 ft.
- D.Fir stump 40", 3 ft. high, bears N.30°W., 35.5 ft.

Stumps have been peeled, treated and covered with metal roof and tagged.

Cor. is along cutting line, approx. 200 ft. South of road #20-7-5.3. Line crossing tag on road near SW. sec. corner.

BLM Resurvey by Harvey E. Wofford & Lester E. Fischer, Cadastral Surveyors, under Group #913, Surveyed Aug. 1976/Aug. 1978 - (DCSO records Vol. 40 Page(s) 16102-03)

The ¼ sec. cor., monumented with an iron post, 1" dia., firmly set, projecting 10" above ground, with brass cap mkd. in 1949, (Cont. Next Page)

TOWNSHIP 20 RANGE 07 POINT IDENTIFIER # 151700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 31 only, T19-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of the original bearing trees:
A Fir snag 27" dia., bears N.28°E., 18 lks. dist., with
healed blaze. (Note: Rec. is S.28°E. per 1949 resurvey
and survey M 87-8 records SE. V.Laugen)
A sawed Fir stump 35" dia., bears N.30°W., 16 lks. dist.,
with healed blaze. (Rec. 14 lks.)
and the remains of a bearing tree mkd. by Price & Tillman:
A sawed Fir stump 44" dia., bears N.29½°E., 53 lks. dist.
with healed blaze.
and a new bearing tree:
A Hemlock 10" dia., bears N.74°W., 17 lks. dist. mkd. ¼
S31 BT.
No other suitable trees available within limits.
Set a 5 ft. steel fence post alongside iron post.

Fd. OK, March 1981, by Les Roberts - M 87-8