

Alias	Description
Alias	Description
Alias	Description
Alias	Description

with 1" dia., cap mkd: WILFORD HAINES 239 SURVEY POINT DRAIN, OREGON, and subsequently perpetuated & recorded by the Douglas County Surveyor in Feb. 1966, monumented with an iron post, 1¼" dia., protruding 8" above the ground, firmly set, with 2¼" brass cap (properly) mkd.

from which the remaining orig. BTs

A burned fir, 48" dia., bears N.45°E., 27 lks., with burned out blaze, no scribe marks visible.

An uprooted fir, 60" dia., bears S.75½°E., 17 lks., with burned out blaze, no scribe marks visible. (Rec. bearing S.5½°E.)

A fir stump hole, bears S.30½°W., 23 lks.

and a bearing object mkd. by Haines in 1961

A vertical rock outcropping, 3 ft. high, 10 ft. long, bears S.68¼°E., 26½ lks., with chisel marks S29 X BO. The X BO. The X has a 1" dia., brass cap, which is attached with a nail, centered over it.

and BTS mkd. by the County Surveyor in Feb. 1966

A burned maple, 11" dia., bears S.40½°E., 39½ lks., with scribe marks T20S R7W S29 CS BT visible on burned blaze.

A burned hemlock, 6" dia., bears S.11°W., 50½ lks., with scribe marks T20S R7W S30 CS BT visible on burned blaze.

and new BTS

A sawed & burned fir stump, 45" dia., bears S.35¾°E., 184½ lks., mkd: T20S R7W S29 BT.

A sawed & burned fir stump, 40" dia., bears N.13½°W., 93½ lks., mkd: T20S R7W S19 BT.

Set a steel fence post alongside the iron post.

Les Roberts - Seneca Jones Timber Co. - April 1999 - M 131-45

Found - 1966 Douglas Co. iron pipe & brass cap.
60" Fir, N.45°E., 17.8' (scar vis.), 1891 BT.
Vertical Rock BO (3.0' x 10.0') bears S.68°E., 17.7', mkd: "29 x BO" by Haines.

Set - 6" Fir, N.70°E., 10.8 ft., (scribed/metal washer/painted red)
8" Fir, N.51°W., 14.6 ft., scribed/metal washer/painted red)
10" Fir, S.76°W., 7.3 ft., scribed/metal washer/painted red)

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 19, 20, 29, & 30

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM resurvey by George M Winter, Cadastral Surveyor, under Group No. 2699, surveyed May/Sept 2013 - (DCSO recs Vol. 58 pgs 23144-5)

The cor. of secs. 19, 20, 29, and 30, perpetuated by Roberts, in 1999, monumented with an iron post, 1 1/4" dia., firmly set, projecting 9 ins. above ground with brass cap (properly) mkd. from which the remains of an original bearing tree

A decayed fir snag, 37" dia., bears N.45°E., 17.8 ft., with a burnt, open blaze.

and a bearing object mkd. by Haines in 1961

A vertical rock outcropping, 3 ft. high, 10 ft. long, bears S.68 1/4°E., 17.9 ft., with chisel marks X S29 visible and a brass cap, 1" dia., nailed into the X.

and the remains of BTs mkd. by Roseberry and Glenn in 1966-67

A decayed fir stump, 38" dia., bears S.33°E., 53.7 ft., with scribe marks 7W S 9 BT visible on an open blaze. (Record, S.35 3/4°E., 121.8 ft.)

A decayed fir stump, 53" dia., bears N.12 1/2°W., 60.9 ft., with no marks visible. (Record, N.13 1/2°W., 61.7 ft.)

and bearing trees mkd. by Roberts

A fir, 10" dia., bears N.70°E., 10.8 ft. with a healed blaze.

A fir, 13" dia., bears S.76°W., 7.3 ft., with a healed blaze.

A fir, 12" dia., bears N.51°W., 14.6 ft. with a healed blaze.

Alongside the cor. is a T-shaped iron rod, 3/4" dia., firmly set, projecting 7" above ground, with brass disk on top, mkd.

WILFORD N HAINES 239 SURVEY POINT DRAIN ORE

NAD 1983 (2011)

Latitude: 43°48'30.07" N Longitude: 123°34'08.25"W

Ronald L Rice - For: Oxbow Timber 1 LLC - April 2015 - M170-3

Found - County surveyors office brass cap dated 1966, with the following accessories:

37" rotted D.Fir snag bears N.45°E., 17.8' - burnt open face

3'x10' vertical rock out cropping chisel marked X S29 with 1" brass disk nailed in X bears S.68 1/4°E., 17.9'

38" rotted D.Fir stump bears S.33°E., 53.7' - scribing visible.

53" Rotted D.Fir stump bears N.12 1/2°W., 60.9' - no marks

10" D.Fir bears N.70°E., 10.8' - healed face.

13" D.Fir bears S.76°W., 7.3' - healed face.

12" D.Fir bears N.51°W., 14.6' - healed face.

Steel post adjacent to corner.