

PRIMARY CORNER DESCRIPTION C C for Secs. 5 & 6 only (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Thos. Todd, under Contract #574, dated May 19, 1891 - (DCSO records Vol. 2 Page(s) 630)

-----  
(At a point 9.20 chs. West of cor. to 31 & 32, T19-7)  
Set a sandstone 21x12x10 ins., 18" in the ground, for closing cor. to secs. 5 & 6, marked CC with 5 notches on E. & 1 on W. faces; from which

- A Fir 36" dia., bears S.78°E., 27 lks. dist., mkd. T20S R7W S5 BT.
- A Fir 14" dia., bears S.61°W., 170 lks. dist. mkd. T20S R7W S6 BT.
- A Fir 40" dia., bears N.30°E., 98 lks. dist. mkd. T20S R7W CC S5 & 6 BT.

Oct. 26, 1891

BLM Resurvey by Norman Price and Thomas Tillman, Cadastral Engineers, under Group #284, Surveyed June/Sept. 1949 - (DCSO records Vol. 31 Page(s) 13010)

-----  
The closing corner, monumented with a sandstone, 12x10x6 ins., above ground, firmly set, marked with a cross on top, CC on N. face, & with 1 groove on W. face; and with an iron rod, 3/4" dia., welded to a 1 1/2" angle iron, 24" above ground, firmly set, from which original bearing trees:

- A Fir snag, 50" dia., bears N.28°E., 98 lks. dist., plainly blazed and healed. (Rec. brg. N.30°E.)
- A splintered Fir stump, 48" dia., bears S.78°E., 21 lks. dist., with partial scribe marks visible on fallen trunk. (Rec. dist., 27 lks.)

and trees marked by the county surveyor:

- A Fir 7" dia., bears S.83 1/4°E., 13 lks. dist. marked CS T20S R7W S6 CC BT.
- A Fir 7" dia., bears S.37 1/4°W., 18 lks. dist. marked CS T20S R7W S6 CC BT.

BLM Resurvey by Harvey E. Wofford & Lester E. Fischer, Cadastral Surveyors, under Group #913, Surveyed Aug. 1976/Aug. 1978 - (DCSO records Vol. 40 Page(s) 16127-28)

-----  
Intersect the S. bdy. of T19S R7W.  
True point for the closing cor. of secs. 5 and 6.  
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

T 19 S R 7 W  
S 31  
S 6 S 5  
T 20 S R 7 W  
C C  
1977

(Cont. Next Page)

TOWNSHIP 20 RANGE 07 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION C C for Secs. 5 & 6 only, (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which

A Fir 33" dia., bears S.41°E., 74 lks. dist. mkd. T20S R7W  
S5 CC BT.

A Fir 15" dia., bears S.36°W., 85 lks. dist. mkd. T20S R7W  
S6 CC BT.

Set a 5 ft. steel fence post alongside iron post.

From this point, the original closing cor. of secs. 5 & 6, bears N.0°01'E., 0.11 chs. dist., monumented with the original sandstone, 24x16x12 ins., firmly set, 12" in the ground, mkd. X on top, with 5 grooves on E. and 1 groove on W. faces, and CC on N. face, and with an iron rod, 3/4" dia., firmly set, projecting 10" above ground, alongside, from which the remains of the original bearing trees;

A Fir snag, 50" dia., bears N.28°E., 98 lks. dist. with healed blaze.

A decayed Fir stump, size indeterminate, bears S.78°E., 21 lks. dist., no marks visible.

and bearing trees mkd. by the County Surveyor, (date unknown)

A Fir 13" dia., bears S.83¼°E., 13 lks. dist., with healed blaze.

A Fir 15" dia., bears S.37¼°W., 18 lks. dist. with healed blaze.

Add the marks AM to corner stone and deposit stone, and reset iron rod at original corner position.