

TOWNSHIP 20 RANGE 07 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION Wit Corner 1/4 Cor Secs 21 & 28

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Thos. E. Todd under Contract No. 574 dated May 19, 1891 - (DCSO recs. Vol. 2 Page(s) 611)

Set post, 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor., mkd: ¼ S on N face; from which

A fir, 24" dia., bears N.2°W., 28 lks., mkd: ¼ S BT.

A fir, 24" dia., bears S.70°W., 56 lks., mkd: ¼ S BT.

Wilford N. Haines - For: Woolley Logging - 1961 - C.S. File 51/222-4 & M21-76

Found - 24" fir, now dead stub, N.2°W., 28 lks.

24" fir, s.70°W., 56 lks., is now gone.

Set - 1"x1"x36" T iron on high bank of logging road.

Scribed- 13" D.Fir S.69°W., 79.6 ft.

18" D.Fir N.57½°E. 292.5 ft. (on East side of Rd R/W

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Mike Stone- Oct. 1962 - C.S. File 49/89-35

Found - Haines "T" iron about 3 ft. downhill from corner (in slide area on upper side of logging road)
Dead Fir snag N.2°W., 18.5 ft. Had been previously opened. Good scribing "4S" plainly visible on old face.

Both Haines BTs alive & in good condition.

12" D.Fir S.69°W., 79.6 ft. scribing still visible.

18" D.Fir N.57½°E. 292.5 ft. scribing still visible.

I move Haines' "T" iron back to true corner position.

Set - Wit. Cor. iron pipe with brass cap mkd: County Surveyor's Office 1962 T20S R7W W C ¼ S21/S28 60 ft. E to Cor" 60' W of ¼ corner.

Haines SW BT, 13" D.Fir scribed "¼S28BT" bears S.25°W., 32.8 ft.

New BTs- 15"R.Cedar N.30°W., 18.8 ft. mkd: WC ¼ S21 CS BT.

Corner lies on very steep East slope. ¼ cor. approx. 40 ft. W of centerline of logging road.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage, J. Rabe, Frank Young - Sept 1966 - C.S. 54/22-7

Found - Brass cap & BTs

Orig. dead fir snag N.2°W., 18.5 ft. now badly burned, no scribe found.

Haines 18" now 24" D.Fir N.57½°E., 292.5 ft. burned scribe "¼B" visible on nearly healed blaze.

Haines button on face. Tree will probably die.

continued next page

TOWNSHIP 20 RANGE 07 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION Wit Corner 1/4 Cor Secs 21 & 28

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Note - Haines 12" now 14" D.Fir S.69°W., 79.4 ft. healed blaze. Alive, only slightly burned.
Bearing & distances above are to true ¼ corner.
15" R.Cedar now dead, N.30°W., 18.9 ft. burned out inside, no scribe.
Haines SW BT bears S.25°W., 32.8 ft. alive & good condition.
New BT - 30" D.Fir N.3°E., 7.0 ft. mkd: WC ¼ S 21 CS BT.
Note - Brass cap only slightly burned mkd. 1962 60 ft. to cor.
Witness corner lies approx. 100 ft. west of center line of Yellow Point Rd. on very steep, East slope.
Orig. corner falls in slide area. No "T" iron found.

Douglas Co. Surveyors Office - V.R. Tracy - Ed Monrean - 6/23/1972 - C.S. File 54/22-15

Found - No trace of brass cap set in 1962 by MEG
18" now 26" D.Fir N.57½°E., 292.5 ft. alive & OK
14" D.Fir stump S.25°W., 32.8 ft. Haines button.
30" D.Fir stump N.3°E., 7.0 ft. all scribe visible, good condition.
At point 60 ft. west of true corner:
Set - Brass cap mkd: "County Surveyors Office 1972 T20S R7W
Wit. Cor. to ¼ Cor. S21 60 ft. E to S28 corner"
No new BTs mkd.
No trees within limits. True corner not set as it falls in slide.

Fd. Ok by D. Edwards 10/1995 - M122-7