

PRIMARY CORNER DESCRIPTION Cor. Secs. 9, 10, 15, & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Thos. E. Todd under Contract No. 574 dated May 19, 1891 - (DCSO recs. Vol. 2 Page(s) 605)

Set sandstone, 18x12x8", 12" in the ground, for cor. to secs. 9, 10, 15, & 16, marked with 4 notches on S & 3 notches on E edges; from which

A cedar, 8" dia., bears N.32°E., 44 lks., mkd: T20S R7W S10 BT.

A fir, 16" dia. bears S.10°E. 80 lks. mkd: T20S R7W S15 BT

A maple, 16" dia., bears S.13°W., 55 lks., mkd: T20S R7W S16 BT.

A cedar, 12" dia., bears N.15°W., 37 lks., mkd: T20S R7W S9 BT.

BLM dependent resurvey by Lynn M. Roseberry & Wm. W. Glenn, Cadastral Surveyors, under Group #350 & 622, surveyed Oct. 1966/May 1967 (DCSO records Vol. 34 Page(s) 14150)

The cor. of secs. 9, 10, 15, & 16, monumented with the orig. broken sandstone, 18x12x8" firmly set, 12" in the ground mkd. with 4 grooves on S face & a cross on the top, from which the remaining orig. BTs:

A burned cedar snag, 20" dia, bears N.32°E., 44 lks., with no marks remaining.

A burned fir, 42" dia., bears S.12°E., 74 lks., with burned out blaze, no scribe marks visible. (Rec. S.10°E., E., 80 lks.)

A burned cedar stump, 20" dia., bears N.15°W., 34 lks., no marks remaining. (Rec. dist. 37 lks.)

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T20S	R7W
S 9	S 10
S 16	S 15
1966	

from which new BTs

A burned maple, 17" dia., bears N.52½°E., 88 lks., mkd: T20S R7W S10 BT.

A burned maple, 21" dia., bears S.32°W., 27½ lks., mkd: T20S R7W S16 BT.

A burned & hollow cedar, 45" dia., bears N.42°W., 85 lks., mkd: T20S R7W S9 BT.

Deposit the orig. cor. stone & set a steel fence post alongside the iron post.

continued next page

TOWNSHIP 20 RANGE 07 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor. Secs. 9, 10, 15, & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Daniel N. Patterson, Cadastral Surveyor under Group No. 2165, surveyed July 2007/Sept. 2008 - (DCSO records Vol. 56 Page(s) 22199)

The cor. of secs. 9, 10, 15, and 16, monumented with an iron post, 2½" dia., firmly set, projecting 4" above the ground, with brass cap (properly) mkd from which the remains of an original bearing tree reported by Roseberry and Glenn in 1966-67

A burnt decayed fir stump, size indeterminate, bears S.12°E., 48.8 ft., with no marks visible.
and new bearing trees

A fir, 14" dia., bears N.89¾°E., 18.0 ft., mkd. T20S R7W S10 BT.

A fir, 7" dia. bears S.68°E. 16.7 ft. mkd. T20S R7W S15 BT

A maple, 10" dia., bears S.27¼°W., 14.2 ft., mkd. T20S R7W S16 BT.

A fir, 10" dia. bears N.0¾°W., 5.9 ft. mkd. T20S R7W S9 BT

Fd. BC & 4 BTs w/steel post adjacent to corner by R.Rice
5/2014 - M168-5