

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 14

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Thos. E. Todd under Contract No. 574 dated May 19, 1891 - (DCSO recs. Vol. 2 Page(s) 592)

Set sandstone, 24x10x10" 18" in the ground for the 1/4 sec. cor. marked 1/4 on N face; from which
A fir, 4" dia., bears N.69°E., 44 lks., mkd: 1/4 S BT.
A maple, 4" dia., bears N.45°W., 28 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Harvey E. Wofford & Lester E. Fischer, Cadastral Surveyors under Group #913, surveyed Aug. 1976/Aug. 1978 - (DCSO records Vol. 40 Page(s) 16104-5)

Point for 1/4 sec. cor. of secs. 13 & 24, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2 1/2" dia., 20" in the ground, with brass cap marked:
T20S R7W
1/4
S 14|S 13
1977 from which
A fir, 25" dia., bears N.6°E., 49 lks., mkd: 1/4 S13 BT.
A fir, 28" dia., bears S.80°W., 60 lks., mkd: 1/4 S14 BT.
Set a 5 ft. steel fence post alongside iron post.

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #1502, surveyed Aug.1989/April 1991 - (DCSO records Vol. 50 Page(s) 19077)

The 1/4 sec. cor. of secs. 13 & 14, monumented with an iron post, 2 1/2" diam., firmly set, projecting 10" above ground, with brass cap mkd.
T20S R7W
1/4
S14 S13
1977
from which bearing trees mkd. by Wofford and Fischer
A fir, 29" dia., bears N.6°E., 49 lks., with healed blaze.
A fir, 32" dia. bears S.80°W., 60 lks., with healed blaze.

Rob Ward - 3/2001 - C.S. File 65/36-18

Found -3 1/4" BLM brass cap properly mkd.
29" D.Fir bears N.6°E., 32.3' healed face.
35" D.Fir bears S.80°W., 39.6' healed face.
New - 18" D.Fir bears S.62°W. 33.0' blazed/scribed "1/4 S14 BT"
18" D.Fir bears S.8°E. 33.1' blazed scribed "1/4 S13 BT"
Steel post adjacent to corner. All BTs have red painted bands & faces plus yellow BT tag.