

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31 only, (West)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #486, dated August 1, 1883 (DCSO records Vol. 1 Page(s) 315)

Set post 6" dia., 4 ft. long, 12" in ground for cor. to secs. 30, 31, 25 and 36, with marked stone, mkd. T20S S30 on NE.; R8W S31 on SE.; R9W S36 on SW.; S25 on NW. faces, with 5 notches on N. and 1 on S. edges, from which
Fir 40" dia., bears N.34°E., 30 lks. mkd. T20S R8W S30 BT.
Fir 36" dia., bears S.66°W., 53 lks. mkd. T20S R9W S36 BT.
Fir 22" dia., bears S.50°E., 23 lks. mkd. T20S R8W S31 BT.
Fir 24" dia., bears N.84°W., 64 lks. mkd. T20S R9W S25 BT.

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #297, Surveyed May 1951/Oct. 1952 - (DCSO records Vol. 27 Page(s) 11333)

Point for the cor. of secs. 30 & 31, at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post 3 ft. long, 2" dia., 28" in the ground with brass cap mkd:
T 20 S * T 20 S
R 9 W * S 30
 * S 31
S 36 * R 8 W
1950

from which
A Fir 20" dia., bears N.11½°E., 33 lks mkd T20S R8W S30 BT
A Fir 20" dia., bears S.34½°E., 34 lks mkd T20S R8W S31 BT

BLM Remonumentation of corner by Wm. Glenn; C. Albert White and James E. Jelley, Cadastral Surveyors, under Group #'s 350 and 635, surveyed April/May 1967 - (DCSO records Vol. 43 Page(s) 16710)

The cor. of sec. 30 & 31 only, monumented with an iron post 2" dia, firmly set, projecting 12" above ground with brass cap mkd. in 1950,
from which remains of bearing trees mkd. in 1950:
A burned Fir 23" dia., bears N.11½°E., 33 lks. dist., no marks visible on open and burned blaze. Rescribed T20S R8W S30 BT on new blaze.
A Fir 23" dia., bears S.34½°E., 34 lks., with healed blaze and a local bearing tree:
A Fir 25" dia., bears N.86½°E., 43 lks. with healed blaze
Set a 5 ft. steel fence post alongside the iron post.

continued next page

PRIMARY CORNER DESCRIPTION Sec Cor for 30 & 31 only, (West)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2313, surveyed March/Aug. 2011 - (DCSO records Vol. 58 Page(s) 22909)

The cor. of secs. 30 and 31 only, on the W. bdy. of T20S R8W bears N.1°14'07"E., 63.50 ft., monumented with an iron post, 2" dia., firmly set, projecting 19" above ground, with a bronze cap (properly) mkd.

from which the remains of the BTs mkd. by Tillman in 1950

A decayed burned fir snag, 17" dia., bears N.11½°E., 21.8 ft., with illegible scribe marks visible on open decayed blaze.

A fir, 30" dia., bears S.34½°E., 22.4 ft., no marks visible and a seed tree tag on the back. A large scar runs 30 ft. up from the base of the tree over the face. and a bearing tree mkd. by Glenn, et al., in 1967

A fir, 34" dia., bears N.88½°E., 28.4 ft., no marks visible. (Record, N.86½°E.) A large scar runs 20 ft. up from the base of the tree over the face.

A steel fence post is alongside the cor., which falls on the uphill side of a very decayed fir stump, 2 ft. dia.

Ron Rice - For: Oxbow Timber 1 LLC - Feb. 2014 - M167-42

Found - 2½" GLO brass cap dated 1950 as referenced by 2011 BLM leaning 08' (set pipe to vertical) with the following accessories:

17" Fir snag bears N.11½°E., 21.8' rotted face

30" Fir bears S.34½°E., 22.4' - large natural scar

34" Fir bears N.88½°E., 28.4' - large natural scar

11" Fir in NE quadrant shows partially healed face un-scribed appears to be 2011 unfinished BLM

BT GLO brass cap marking the E¼ Corner S36 bears S.1°24'53"W 63.87'

Steel post adjacent to corner