

PRIMARY CORNER DESCRIPTION W. 1/4 cor. for Sec. 18 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #486, dated August 1, 1883 (DCSO records Vol. 1 Page(s) 317)

-----  
Set post 4" dia., 4 ft. long, with marked stone, 12" in ground for 1/4 sec. cor. marked 1/4 S on W. face; from which  
Fir 18" dia., bears N.71°W., 10 lks. dist. mkd. 1/4 S BT.  
Fir 20" dia., bears S.70°E., 15 lks. dist. mkd. 1/4 S BT.

GLO Resurvey by Thomas Tillman; Raymond Bicknell; Hans Thielsen; & Joseph Gawron, Cadastral Surveyors, under Group #305, Surveyed Aug. 1953/Sept. 1954 - (DCSO records Vol. 29 Page(s) 12349-50)

-----  
The 1/4 sec. cor., determined at record bearing and distance from the original bearing trees:

A turned out Fir 16" dia., bears N.71°W., 10 lks. dist., marked with a rotted blaze.

A Fir snag 24" dia., bears S.70°E., 15 lks. dist. mkd. BT 1/4 S on bark.

At the corner point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd: \*1/4 S 18  
1954

from which

A Fir 26" dia., N.41 1/4°E., 31 lks. dist. mkd. 1/4 S18 BT.

A Hemlock 20" dia., S.30 1/4°E., 5 lks. dist. mkd. 1/4 S18 BT.

Corner falls on a spur sloping S.70°W.

Douglas Co. Surveyors Office - John M. Powell, and crew - Oct. 14, 1965 - C.S. File 53/66

-----  
Found - GLO brass cap, 1954.

26" Fir N.41 1/4°E., 31 lks. scribed 1/4 S18 BT.

20" Hemlock S.40 1/4°E., 5 lks. This tree is blown down

Set brass cap for Witness Corner 40 ft. West mkd.

County Surveyors Office

W.C.

40' West

TO

1/4 \*S 18

\*T 20 S

\*R 8 W

1965

New BTs- 12" Hemlock N.72°W., 7.8 ft. scribed WC S18 CS BT

12" Hemlock N.40 1/2°E., 4.3 ft. scribed WC S18 CSBT

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 18 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM Remonumentation of corner by Wm. Glenn; C. Albert White and James E. Jelley, Cadastral Surveyors, under Group #'s 350 and 635, surveyed April/May 1967 - (DCSO records Vol. 43 Page(s) 16714)

-----  
The true point for the 1/4 sec. cor. of sec. 18 only, determined from the remaining bearing tree marked in 1954, this point falls in a cut bank of a gravel road and is impractical to monument.

A Fir 28" dia., bears N.41 1/4°E., 31 lks. dist., with fragmentary scribe marks visible on burned blaze.  
From this point, a Witness Corner established by the County Surveyor in 1965, bears East, 66 1/2 lks. dist., monumented with an iron pipe 1" dia., firmly set, projecting 14" above ground with brass cap as marked in 1965, from which the remains of the trees mkd. by the County Surveyor in 1965

A Hemlock stump 12" dia., bears N.46°E., 7 lks. dist., with scribe marks BT visible on unhealed blaze.  
Set a 6 ft. steel fence post alongside the iron post.

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #2000, surveyed Jan./March 2005 - (DCSO rec. Vol. 55 Page(s) 21752-3)

-----  
The 1/4 sec. cor. of sec. 18 only, determined at record bearing and distance from the remains of a bearing tree mkd. by Tillman, et al., in 1953-54.

A fir stump, 26" dia., bears N.41 1/4°E., 20.5 ft., with no marks visible on partially healed blaze.  
Corner is located on edge of a graveled road, where it is impractical to establish a permanent monument.

From this point, a witness corner established by the Douglas County Surveyor's Office in 1965, and reported by Glenn et. al., in 1967, bears East, 43.89 ft., monumented with an iron post, 1" dia., firmly set, projecting 13" above the ground, with brass cap (properly) mkd.

from which the remains of a bearing tree mkd. by the Douglas County Surveyor's Office in 1965 and reported by Glenn, et. al., in 1967

A decayed hemlock stump, size indeterminate, bears N.46°E., 4.6 ft., no marks visible.  
and new bearing trees

A fir, 7" dia., bears N.68 1/4°E., 13.0 ft., mkd. X BT.

A fir, 9" dia., bears N.37 1/2°W., 3.8 ft., mkd. WC S18 BT.  
There is a steel fence post alongside the corner.

continued next page

PRIMARY CORNER DESCRIPTION W. 1/4 cor. for Sec. 18 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2313, surveyed March/Aug. 2011 - (DCSO records Vol. 58 Page(s) 22894)

The 1/4 sec. cor. of sec. 18 only, on the W. bdy. of T20S R8W determined at record dist. from the remains of a bearing tree marked by Tillman, et al., in 1953-54

A decayed fir stump, 22" dia., bears N.41 1/4°E., 20.5 ft., with the burned remains of a healed blaze.

and the remains of a bearing tree mkd. by person(s) unknown

A decayed fir stump, 27" dia., bears N.6 3/4°E., 20.4 ft., no marks visible, with a bearing tree tag mkd. S.5°W., 20 (illegible) ft., dated 1967 and 1978.

From this point the witness cor. established by the Douglas County Surveyor's Office in 1965, monumented with an iron post, 1" dia., firmly set, projecting 14" above ground, with bronze cap mkd. COUNTY SURVEYORS OFFICE WC 40' WEST TO 1/4 | S18 T20S R8W 1965, bears East, 40.00 ft. (Record, 43.89 ft.) from which the remains of a bearing tree mkd. by the Douglas County Surveyor's Office

A decayed hemlock stump, size indeterminate, bears N.46°E., 4.6 ft., no marks visible.

and bearing trees mkd. by Graham in 2005

A fir, 9" dia., bears N.68 1/4°E., 13.0 ft., with a healed double blaze.

A fir, 11" dia., bears N.37 1/2°W., 3.8 ft., with a healed blaze.

A steel fence post is alongside the witness cor., which falls on the top of the cut bank, 35 ft. N. of an overgrown graveled road, 10 ft. wide, bears N.85°E. and S.85°W.

At the corner point

Drive an aluminum rod, 36" long, 3/4" dia., 20" in the ground, with alum. cap mkd.

```

      T 20 S
      R 9 W | R 8 W
              | 1/4 S 18
              2011

```

Corner falls on the cut bank of an overgrown gravel road, 10 ft. wide, bears N.85°E. and N.40°W. Drive an aluminum post alongside the true cor.