TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 6 & 7

Alias Description
Alias Description
Alias Description
Alias Description

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 498)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked ¼ S on N face; from which
Fir, 24" dia., bears S.15°W., 66 lks., mkd: ¼ S BT.
Fir, 20" dia., bears N.21°W., 30 lks., mkd: ¼ S BT.

BLM dependent resurvey by Thomas A Tillman, Raymond M. Bicknell, Han W. Thielsen & Joseph S. Gawron, Cadastral Engineers, under Group No. 305 surveyed Aug. 1953 thru Sept. 1954 - (DCSO recs. Vol. 29 Page(s) 12389-90)

The ¼ sec. cor. of secs. 6 & 7, determined at rec. bearing & dist. from the remaining orig. BTs:
A fir, 36" dia., bears N.21°W., 30 lks., mkd: BT ¼S on bark.
A fir, 31" dia., bears S.15°W., 56 lks., mkd: BT ¼S on bark (Rec. dist. 66 lks.)
At the corner point
Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap marked: ¼ S 6 / S 7 1954

Ronald L Rice - For: Oxbow Timber 1 LLC - Nov. 2015 - M170-30

Found - GLO Brass cap not fd. The ¼ corner monument between sections 6 and 7 was search for and not found. Corner was remonumented by distance - distance intersection from the original BT stumps, using record distances from the 1960 BLM dependent resurvey.
36" metal capped D.Fir stump bears N.18°W., (record N.21°W.) 19.8' - healed face
31" D.Fir stump bears S.15°W., 37.0' - healed face
New - ⅝"x30" rebar and 2-1/2" aluminum cap marked
T20S R8W
¼ S 6 / S 7
2015
54633LS

11" Alder bears N.22°W., 11.7', bark scribed ¼ S6 BT
16" D.Fir bears N.39°E. 20.4' blazed scribed ¼ S6 BT
14" D.Fir bears S.34°E. 10.2' blazed, scribed ¼S7 BT
14" D.Fir bears S.74°W. 32.9' blazed scribed ¼ S7 BT
Steel post adjacent to corner.