



PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 20

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM dependent resurvey by Edith M Forkner and Aaron M. Graham, Cadastral Surveyors, under Group #2312, surveyed July/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22964)

The ¼ sec. cor. of secs. 19 & 20, monumented with an iron post, 1" dia., firmly set, projecting 4" above ground, with a brass cap (properly) mkd.

from which the remains of the original bearing trees

A cedar stump, 64" dia., bears S.53°E., 27.7 ft., no marks visible.

A fir snag, 72" dia., bears N.60°W., 31.0 ft., with no marks visible on open blaze.

and the bearing trees mkd. by Tillman, et al., in 1953-54

A hemlock, 15" dia., bears N.82°E., 54.8 ft., no marks visible. (Record, N.82¾°E.)

A fir, 27" dia., bears N.81½°W., 33.7 ft., no marks visible.

and new bearing trees

A fir, 17" dia., bears N.64°E., 11.8 ft., mkd. ¼ S20 BT.

A fir, 16" dia., bears N.36¼°W., 4.6 ft., mkd. X BT.

From the corner

S., 190 ft., creek, 5 ft. wide, course N.40°E.

Ronald L Rice - For: Oxbow Timber 1 LLC - Jan. 2015 - M169-8

- Found - 1954 GLO brass cap with the following accessories:
- 64" Cedar stump bears S.53°E., 27.7' - no marks
  - 72" D.Fir snag bears N.60°W., 31.0' - open face no scribing
  - 15" Hemlock snag bears N.82°E., 54.8' - no marks
  - 27" D.Fir snag bears N.81½°W., 33.7' - no marks
  - 17" D.Fir bears N.64°E., 11.8' - scribing visible
  - 16" D.Fir bears N.36¼°W., 4.6' - scribing visible
- Steel post adjacent to corner