

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Pages 492-3)

Set post, 6" dia., 4 ft. long, with marked stone, 12" in ground, for cor. to secs. 17, 18, 19, & 20, mkd. T 20S S 17 on NE, R 8W S 20 on SE, S 19 on SW, S 18 on NW face, with 3 notches on S & 5 on E edge; from which

- Fir, 40" dia., bears S.79°E., 19 lks. mkd: T20S R8W S20 BT
- Fir, 40" dia., bears N.76°W., 42 lks., mkd: T20S R8W S18 BT
- Fir, 40" dia., bears S.70°W., 56 lks. mkd: T20S R8W S19 BT
- Fir, 20" dia., bears N.63°E., 70 lks. mkd: T20S R8W S17 BT

BLM dependent resurvey by Thomas A Tillman, Raymond M. Bicknell, Han W. Thielsen & Joseph S. Gawron, Cadastral Engineers, under Group No. 305 surveyed Aug. 1953 thru Sept. 1954 - (DCSO recs. Vol. 29 Page(s) 12382-3)

The cor of secs 17, 18, 19, & 20 determined from the orig BTs
A fir snag, 28" dia., bears N.63°W., 70 lks, marked with a healed blaze.
A fir snag, 47" dia., bears S.77½°E., 19 lks., marked with a healed blaze. (Rec. bearing S.79°E.)
A fir snag, 57" dia., bears S.70°W., 54 lks., marks BT 19 remaining on bark (Rec. dist. 56 lks.)
A fir, 62" dia., bears N.76°W., 43 lks., with marks S 8 W remaining on bark. (Rec. dist. 42 lks.)

At the corner point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked

T20S	R8W
<u>S 18</u>	<u>S 17</u>
S 19	S 20
1954	

from which new BTs

- A fir, 45" dia., bears N.79½°E., 115 lks., mkd: T20S R8W S17 BT.
- A hemlock, 18" dia., bears S.12¼°E., 34 lks., mkd: T20S R8W S20 BT.
- A fir, 52" dia., bears S.49½°W., 80 lks., mkd: T20S R8W S19 BT.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16748-9)

The corner of secs. 17, 18, 19, & 20 monumented with an iron post, 2" dia., firmly set, projecting 4" above ground with brass cap (properly) mkd. continued next page

Alias	Description
Alias	Description
Alias	Description
Alias	Description

from which the remains of the orig. BTs
 A burned fir snag, 20" dia., bears N.63°W., 70 lks, with healed blaze.
 A burned fir snag, 47" dia., bears S.77½°E., 19 lks., with healed blaze.
 A burned fir snag, 57" dia., bears S.70°W., 54 lks., no marks visible on decayed blaze. Rescribed T20S R8W 19 BT on new blaze.
 A root hole, bears N.76°W., 43 lks., with a down fir alongside, 62" dia., no marks visible.
 and the remains of the BTs marked in 1954
 A root hole, bears N.79½°E., 115 lks., with a down fir, 45" dia., no marks visible.
 A hemlock snag, 18" dia., bears S.12¼°E., 34 lks., no marks remaining on burned blaze. Rescribed T20S R8W S20 BT on new blaze.
 A root hole, bears S.49½°W., 80 lks., with a down fir, 52" dia., no marks remaining on burned blaze.
 and new BTs
 A cedar snag, 50" dia., bears N.56°E., 127 lks., mkd: T20S R8W S17 BT.
 A hemlock snag, 10" dia., bears N.16½°W., 35½ lks., mkd: T20S R8W S18 BT.
 Set a 5 ft. steel fence post alongside the iron post.

Robert Dean, LS 1808 & Wm. J. Ruppert, LS 866 - For: International Paper Co. - 3/30/1983 - M93-80 & C.S. 58/204(N)

 Found - 1¼" galv. IP w/2½" GLO BC mkd: T20S R8W S18 S17 S19 S20 1954, (found buried 12" in slide area, leaning NE I reset to vertical) from which
 52" cedar stump, face visible, bears N.56°20'E., 84.3 ft. (rec. per 1967 remonumentation N.56°E., 83.82 ft.)
 45" fir stump bears S.78°05'E., 13.0 ft. (rec. per orig. GLO notes S.79°E., 12.54 ft.)
 46" snag w/T20S R8W S19 BT visible, bears S.70°16'W., 34.3 ft. (rec. per orig. GLO notes S.70°W., 36.96 ft.)
 New BTs- 6" D.Fir scribed T20S R8W S17 BT bears N.58°23'E., 40.5 ft.
 5" D.Fir scribed T20S R8W S20 BT bears S.13°30'E., 7.2 ft.
 5" D.Fir scribed T20S R8W S19 BT bears S.42°53'W., 18.2 ft.
 9" Alder, bark scribed T20S R8W S18 BT bears N.58°47'W., 27.1 ft.

Cont.

PRIMARY CORNER DESCRIPTION Cor. Secs. 17, 18, 19, & 20

Alias	Description

BLM dependent resurvey by Edith M Forkner and Aaron M. Graham, Cadastral Surveyors, under Group #2312, surveyed July/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22964-5)

The cor. of secs. 17, 18, 19, & 20, monumented with an iron post, 2" dia., firmly set, projecting 4 ins. above ground, with a brass cap (properly) mkd.

from which the remains of the original bearing trees

A decayed fir stump, 20" dia., bears N.63°E., 46.2 ft., no marks visible.

A decayed fir stump, 42" dia., bears S.77½°E., 12.5 ft., no marks visible.

A fir snag, 43" dia., bears S.70°W., 35.6 ft., no marks visible.

and the remains of a BT mkd. by Glenn, et al., in 1967

A cedar stump, 50" dia., bears N.56°E., 83.8 ft., no marks visible.

and the BTs mkd. by Dean, in 1983

A fir, 18" dia., bears N.58¼°E., 40.7 ft., with a healed blaze.

A fir, 17" dia., bears S.14¾°E., 6.7 ft., with a healed blaze.

A fir, 13" dia., bears S.42°W., 17.1 ft., with a healed blaze.

An alder, 13" dia., bears N.58¼°W., 26.6 ft., with illegible scribe marks visible on bark.

Corner falls on a N. slope.

A steel fence post is alongside the cor.