

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 496)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked ¼ S on W face; from which
Cedar, 36" dia., bears S.60°W., 42 lks., mkd: ¼ S BT.
Cedar, 24" dia., bears N.55°E., 29 lks., mkd: ¼ S BT.

BLM dependent resurvey by Thomas A Tillman, Raymond M. Bicknell, Han W. Thielsen & Joseph S. Gawron, Cadastral Engineers, under Group No. 305 surveyed Aug. 1953 thru Sept. 1954 - (DCSO recs. Vol. 29 Page(s) 12387-8)

The ¼ sec. cor. of secs. 7 & 8, determined at rec. bearing & distance from the orig. BTs:

A cedar, 24" dia., bears N.55°E., 29 lks., with marks BT ¼ S visible on partially healed blaze.

A cedar, 48" dia., bears S.60°W., 42 lks., marked with a healed blaze.

At the corner point

Set an iron post, 3 ft. long, 1" dia., 8" in solid rock, with brass cap marked:

¼
S 7 | S 8
1954

from which new BTs

A cedar, 13" dia., bears S.21½°E., 47 lks., mkd: ¼ S8 BT.

A cedar, 30" dia., bears N.34¼°W., 35 lks., mkd: ¼ S7 BT.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2670, Surveyed May 2012/June 2013 - (DCSO records Vol. 58 Pages 23047-8)

The 1/4 sec. cor. of secs. 7 and 8, monumented with an iron post, 1" dia., firmly set, with top flush with the surface of the ground, with a brass cap (properly) mkd.

from which the remains of the original bearing trees

A decayed cedar stump, 24" dia., bears N.55°E., 19.1 ft., no marks visible.

A decayed cedar stump, 58" dia., bears S.60°W., 23.4 ft., axe mark visible in face. (Record, 27.7 ft.)

and new bearing trees

An alder, 13" dia., bears S.51¾°E., 24.4 ft., mkd. ¼ S8 BT

A cedar, 8" dia., bears S.76°W., 69.3 ft., mkd. ¼ S7 BT.

At N.0°12' 34" W.:

At 5 ft., Creek, 10 ft. wide, course N.75°W.