

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4, T21-8

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #486, dated August 1, 1883 (DCSO records Vol. 1 Page(s) 453)

 Set post 4" dia., 4 ft. long, with marked stone, 12" in ground, for cor. to secs. 33, 34, 3 & 4, marked T20S S34 on NE.; R8W S3 on SE.; T21S S4 on SE.; S33 on NW. faces, with 3 notches on E. & W., edges; from which

- Fir 6" dia., bears N.55°W., 22 lks. dist. mkd. T20S R8W S33 BT.
- Fir 6" dia., bears N.35°E., 33 lks. dist. mkd. T20S R8W S34 BT.
- Fir 10" dia., bears S.47°E., 36 lks. dist. mkd. T21S R8W S3 BT.
- Fir 5" dia., bears S.24°W., 25 lks. dist. mkd. T21S R8W S4 BT.

GLO Resurvey by Norman D. Price and George Rigby, Cadastral Engineers, under Group #282, Surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11393)

 The Sec. Cor., the locus of which is determined by reference to the record distances from the old NE., SE., and SW. bearing trees.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd:

T 20 S R 8 W
<u>S 33*S 34</u>
S 4*S 3
T 21 S
1945

from which

- A Fir 14" dia., bears N.27°E., 33 lks. dist., with healed blaze. (Old BT)
- A Fir 28" dia., bears S.44°45'E., 36 lks. dist., with blaze healed. (Old BT)
- A Fir 18" dia., bears S.24½°W., 25 lks. dist. with blaze healed. (Old BT)
- A Fir 20" dia., bears S.70°W., 43 lks. dist. mkd. T21s R8W S4 BT. (New BT)
- A Fir 20" dia., bears N.61°W., 60 lks. dist. mkd. T20S R8W S33 BT. (New BT)

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4, T21-8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM Remonumentation of corner by Wm. Glenn; C. Albert White and James E. Jelley, Cadastral Surveyors, under Group #'s 350 and 635, surveyed April/May 1967 - (DCSO records Vol. 43 Page(s) 16706)

The sec. cor. monumented with an iron post 2" dia., firmly set, projecting 14" above ground with brass cap mkd. in 1945, from which the remains of the original bearing trees:

A burned Fir snag 15" dia., bears N.27°E., 33 lks. dist. with healed blaze.

A burned Fir 32" dia., bears S.44 3/4°E., 36 lks. dist. with healed blaze.

A burned Fir snag 20" dia., bears S.24 1/2°W., 25 lks. dist. with no marks remaining on burned blaze.

and the remains of the bearing trees mkd. in 1945:

A burned Fir 25" dia., bears S.70°W., 43 lks. dist., with healed blaze.

A burned Fir 25" dia., bears N.61°W., 60 lks. dist. with healed blaze.

and a new bearing tree:

A Fir 18" dia., bears N.11°E., 48 lks. dist. mkd. T20S R8W S34 BT.

Set a 5 ft. steel fence post alongside the iron post.

Survey by Ronald E. Stuntzner - For: Coos Head Timber Co. - Nov. 1968 - C.S. File 55/99

Found existing brass cap set by U.S. Cadastral Engineers and 2 bearing trees in section 33.

Set three BTs as follows:

Bark scribed 24" D.Fir stump, S.70°W., 28.1 ft.

Bark scribed 42" D.Fir stump, S.47°E., 88.9 ft.

Bark scribed 22" D.Fir stump, N.37°45'E., 50.0 ft.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2285, surveyed Aug. 2009/ Feb. 2010 (DCSO records BLM plat 2011 & Vol. 56 Page(s) 22263-65)

The cor. of cor. 3, 4, 33, and 34. on the N. bdy. of the Tp., remonumented by Price and Rigby in 1945, utilized by Tillman in 1950. rehabilitated by Glenn, et al., in 1967, and by Stuntzner, PE No. 6245. in 1968; monumented with an Iron post. 2" dia., firmly set, projecting 11", above ground, with brass cap (properly) mkd. from which the remains of the original BTs

A burned decayed fir stump, size indeterminate, bears S.44 3/4°E., 23.8 ft., no marks visible.

continued next page

PRIMARY CORNER DESCRIPTION Sec Cor for 33 & 34; 3 & 4, T21-8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

The remains of a fir stump, size indeterminate, bears S.24½°W., 16.5 ft., no marks visible.
and the remains of the bearing trees mkd. by Price and Rlgby
A burned decayed fir stump, 25" dia., bears S.70°W., 28.4 ft., no marks visible.
A burned decayed fir stump. 25" dia., bears N.61°W., 39.6 ft., with scribe marks 3 BT and other illegible scribe marks visible on open blaze.
and the remains of a BT mkd. by Glenn, et al.
The remains of a fir stump, size indeterminate, bears N.4°E., 31.7 ft., no marks visible. (Record, N.11°E.)
and the remains of the BTs mkd. by Stuntzner
A decayed fir stump, 26" dia., bears N.37¾°E., 50.0 ft., no marks visible.
A decayed fir stump, 47" dia., bears S.46½°E., 88.9 ft., with scribe marks S3 R8W visible on bark.
and new bearing trees
A fir, 11" dia., bears N.49°E., 54.4 ft., mkd. T20S R8W S34 BT.
A fir, 14" dia., bears S.13½°E., 15.0 ft., mkd. T21S R8W S3 BT.
A fir, 13" dia., bears S.44¼°W., 26.3 ft., mkd. T21S R8W S4 BT.
A fir, 9" dia. bears N.66°W.. 24.4 ft mkd. T20S R8W S33 BT
A steel fence poet with a BLM BT tag is alongside the cor.
Corner is located in young timber, on the W. edge near the S. end of a strip of land with no timber and dense undergrowth, 50 ft. wide, bears N.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

BLM dependent resurvey by Edith M Forkner and Aaron M. Graham, Cadastral Surveyors, under Group #2312, surveyed July/Oct.. 2011 - (DCSO records Vol. 58 Page(s) 22953)

The cor. of secs. 3, 4, 33, & 34, on the S. bdy. of the Tp., monumented with an iron post, 2" dia., firmly set, projecting 11" above ground, with brass cap and accessories as described in the 2009-10 official survey by Forkner.