

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 476)

-----  
Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked 1/4 S on W face; from which  
Hemlock, 8" dia., bears N.72°E., 18 lks., mkd: 1/4 S BT.  
Hemlock, 10" dia., bears S.87°W., 19 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Thomas A. Tillman, under Group # 292, Surveyed June/Oct. 1950 (DCSO recs Vol 27 Pages 11347-8)

-----  
The 1/4 sec. cor. of secs. 27 & 28, determined at the rec. bearing & dist. from the orig. SW BT as follows:

A hemlock snag, 16" dia., bears S.87°W., 19 lks., with the scribe marks 1/4 S plainly visible on the opened blaze.

At the corner point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap marked:

1/4  
S 28 | S 27  
1950

from which new BTs

A fir, 38" dia., bears S.31°E., 43 lks., mkd: 1/4 S27 BT.

A fir, 24" dia., bears N.37°W., 59 lks., mkd: 1/4 S28 BT.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16732)

-----  
The 1/4 sec. cor. of secs. 27 & 28, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.

from which the remains of the orig. BT

A burned & decayed hemlock stump, 16" dia., bears S.87°W., 19 lks., no marks remaining.

from which the remains of the BTs mkd. in 1950

A sawed & burned fir stump, 38" dia., bears S.31°E., 43 lks., no marks remaining on burned blaze. Rescribed 1/4 S27 BT on new blaze.

A root hole, bears N.37°W., 59 lks., with a down & sawed fir stump alongside, 24" dia., no marks remaining.

and a new BT

A sawed & burned fir stump, 25" dia., bears N.73°W., 82 1/2 lks., mkd. 1/4 S28 BT.

Set a 6 ft. steel fence post alongside the iron post.

continued next page

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Edith M Forkner and Aaron M. Graham, Cadastral Surveyors, under Group #2312, surveyed July/Oct.. 2011 - (DCSO records Vol. 58 Page(s) 22955-6)

-----  
The ¼ sec. cor. of secs. 27 & 28, monumented with an iron post, 1" dia., firmly set, projecting 10" above ground, with a brass cap (properly) mkd.

from which the remains of a BT mkd. by Tillman in 1950

A decayed fir stump, 22" dia., bears S.31°E., 28.4 ft., no marks visible.

and the remains of a BT mkd. by Glenn, et al., in 1967

A decayed fir stump, size indeterminate, bears N.73°W., 54.5 ft., no marks visible.

and new bearing trees

A fir, 16" dia., bears S.86½°E., 11.8 ft., mkd. ¼ S27 BT.

A fir, 11" dia., bears N.19¼°W., 11.2 ft., mkd. ¼ S28 BT.

A steel fence post is alongside the cor.

Corner falls in a fir plantation