

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 16

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 479)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked ¼ S on W face; from which
Hemlock, 12" dia., bears S.32°W., 22 lks., mkd: ¼ S BT.
Fir, 40" dia., bears S.87°E., 14 lks., mkd: ¼ S BT.

BLM dependent resurvey by Thomas A Tillman, Raymond M. Bicknell, Han W. Thielsen & Joseph S. Gawron, Cadastral Engineers, under Group No. 305 surveyed Aug. 1953 thru Sept. 1954 - (DCSO recs. Vol. 29 Page(s) 12369)

Point for the ¼ sec. cor. of secs. 15 & 16, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

¼
S 16 | S 15
1954

from which

- A fir, 50" dia., bears S.8°E., 4½ lks., mkd: ¼ S15 BT.
- A hemlock, 11" dia., bears N.44°W., 9 lks., mkd: ¼ S16 BT.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jolley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16735-6)

The ¼ sec. cor. of secs. 15 & 16, monumented with an iron post, 1" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd.

from which BTs mkd. in 1954

A root hole, bears S.8°E., 4½ lks., with a down fir alongside, 50" dia., no marks remaining on burned blaze.

A burned hemlock stump, size indeterminate, bears N.44°W., 9 lks., no marks remaining.

and new BTs

A fir stump, 54" dia, bears S.72°E., 91 lks. mkd: ¼ S15 BT

A hemlock snag, 10" dia., bears S.81°W., 33 lks., mkd: ¼ S16 BT.

Set a 6 ft. steel fence post alongside the iron post.

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 16

Alias	Description

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #2000, surveyed Jan./March 2005 - (DCSO rec. Vol. 55 Page(s) 21764)

The ¼ sec. cor. of secs. 15 and 16, monumented with an iron post, 1" dia., firmly set, projecting 4" above the ground, with brass cap (properly) mkd. from which the remains of BTs mkd. by Tillman, et al., in 1953-54

A root hole bears S.8°E., 3.0 ft., with a down decayed fir lying alongside, size indeterminate, no marks visible.

A hemlock stump, 54" dia., bears N.44°W., 5.9 ft., no marks visible.

and new bearing trees

A fir, 14" dia., bears N.55¼°E., 13.4 ft., mkd. ¼ S15 BT.

A fir, 14" dia., bears S.61°W., 20.4 ft., mkd. ¼ S16 BT.

There is a steel fence post alongside the corner.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2670, Surveyed May 2012/June 2013 - (DCSO records Vol. 58 Pages 23042-3)

The ¼ sec. cor. of secs. 15 & 16, monumented with an iron post, 1" dia., firmly set, projecting 4" above ground, with a brass cap (properly) mkd. from which the remains of a BT mkd. by Tillman, et al. in 1953-54

A hemlock stump, 54" dia., bears N.44°W., 5.9 ft. , no marks visible.

and the bearing trees mkd. by Graham in 2005

A fir, 15" dia., bears N.55¼°E., 13.4 ft. , with a healed blaze.

A fir, 15" dia., bears S.61°W., 20.4 ft. , with a healed blaze.