

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 476)

Set post 4" dia., 4 ft. long, in mound of stone, 18" high, 3½ ft. sq. at base, for qr. sec. cor. marked ¼ S on N face; from which there are no witness trees.

BLM dependent resurvey by Thomas A. Tillman, under Group # 292, Surveyed June/Oct. 1950 (DCSO recs Vol. 27 Page 11347)

Point for the ¼ sec. cor. of secs. 27 & 34, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

¼ $\frac{S\ 27}{S\ 34}$
1950

from which

- A hemlock, 28" dia., bears N.71½°W., 40 lks. mkd: ¼ S27 BT
- A fir, 40" dia., bears S.30¼°E., 80 lks., mkd: ¼ S34 BT.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16731-2)

The ¼ sec. cor. of secs. 27 & 34, monumented with an iron post, 1" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd.

from which the remains of the BTs mkd. in 1950

- A root hole, bears N.71½°W., 40 lks. with the charred remains of a down hemlock alongside no marks remaining.
- A root hole bears S.30¼°E., 80 lks. with down & burned fir stump alongside, 31" dia., no marks remaining on burned blaze.

and new BTs

- A burned cedar, 20" dia., bears N.25°E., 72 lks., mkd: ¼ S27 BT.

- A burned sawed fir stump, 25" dia., bears S.10°E., 140 lks., mkd: ¼ S34 BT.

Set a 6 ft. steel fence post alongside the iron post.

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #2000, surveyed Jan./March 2005 - (DCSO rec. Vol. 55 Page(s) 21761-2)

The cor. of secs. 27 and 34, monumented with an iron post, 1" dia., firmly set, projecting 1 in. above the ground, with brass cap (properly) mkd. continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias	Description
Alias	Description
Alias	Description
Alias	Description

from which the remains of a BT mkd. by Tillman in 1950
A root hole bears S.30¼°E., 52.8 ft., alongside of which is a down decayed fir, size indeterminate, no marks visible.
and the remains of BTs mkd. by Glenn, et al., in 1967
A cedar snag, 20" dia., bears N.25°E., 47.5 ft., no marks visible.
A burned decayed fir snag, 22" dia., bears S.10°E., 92.4 ft., with scribe marks S 4 B visible on open blaze.
and new bearing trees
A fir, 9" dia., bears S.66½°E., 13.7 ft., mkd. ¼ S34 BT.
A fir, 12" dia., bears N.7¾°W., 15 ft., mkd. ¼ S27 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2780, surveyed March/Aug. 2015 - (DCSO records Vol. 58 Page(s) 23443-5 & Plat T20-8 2016-1)

The ¼ sec. cor. of secs. 27 & 34, monumented with an iron post, 1" dia., firmly set, projecting 2" above ground, with a brass cap, oriented W., (properly) mkd.
from which the remains of a BT mkd. by Tillman in 1950
A root hole bears S.30¼°E., 52.8 ft.
and the remains of the BTs mkd. by Glenn. et al., in 1967
A burned cedar snag, 19" dia., bears N.22°E., 47.5 ft., no marks visible. (Record, N.25°E.)
A burned decayed fir snag, 21" dia., bears S.11°E., 92.4 ft., no marks visible. (Record, S.10°E.)
and the BTs mkd. by Graham in 2005
A fir, 11" dia., bears S.66½°E., 13.7 ft., with a healed blaze and a Mag Nail at the base on the right side center.
A fir, 14" dia., bears N.7¾°W., 15.0 ft.. with a healed blaze and a Mag Nail at the base on the right side center.
A steel fence post is alongside the monument.