

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #486, dated August 1, 1883 (DCSO records Vol. 2 Page(s) 462)

Set post 6" dia., 4 ft. long, with marked stone 12" in ground, for qr. sec. cor., marked ¼ S on N. face; from which
Fir 18" dia., bears N.10°E., 19 lks. dist. mkd. ¼ S BT.
Fir 12" dia., bears S.70°W., 25 lks. dist. mkd. ¼ S BT.

GLO survey by C.M. Collier, Deputy Surveyor, under Group #580 dated June 23, 1891 - (DCSO records Vol. 2 Page(s) 503)

Failed to find the corners on the N. bdy. of T20S R8W, except those on the N. bdy. of sec. 1. After diligent search I fail to find any other of the original marks of this line or any marks of lines coming in from the South. (This excerpt was taken from Vol. 2 Pg. 501)
(35.70 chs.)

Find post about 4" dia., firmly set in ground mkd. ¼ S on N. face, from which
A Fir 10" dia., bears S.82½°W., 24 lks. dist., mkd. ¼ S BT
A Fir 24" dia., bears N.13°W., 17 lks. dist. mkd. ¼ S BT.
There were no lines or blazes leading to this from either side. I destroyed said post and marks.

(40.00 chs.) (S.88°47'W.)
Set post 4 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor. mkd. ¼ S on N. face; from which
A Fir 20" dia., bears N.15°W., 29 lks. dist. mkd. ¼ S BT.
A Fir 24" dia., bears S.12°W., 13 lks. dist. mkd. ¼ S BT.

BLM Resurvey by Marvin J. Lytle and Palmer Norseth, under Group #298, surveyed May/Aug. 1952 - (DCSO records Vol. 31 Page(s) 12916)

Point for the ¼ sec. cor., as determined from the original bearing trees:
A Fir 25" dia., bears N.15°W., 29 lks. dist., with healed blaze facing the corner.
A Fir 30" dia., bears S.12°W., 13 lks. dist., with healed blaze facing the corner.

At the corner point
Set an iron post, 3 ft. long, 1" dia., 26" in the ground, with brass cap mkd:
¼ S 34
S 3
1952

(Cont. Next Page)

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; & 34, T19-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Remonumentation of corner by Wm. Glenn; C. Albert White and James E. Jelley, Cadastral Surveyors, under Group #'s 350 and 635, surveyed April/May 1967 - (DCSO records Vol. 43 Page(s) 16717)

The ¼ sec. cor. of secs. 3 & 34, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground with brass cap mkd. in 1952,

from which the original bearing trees:

A Fir 26" dia., bears N.10°W., 29 lks. dist., with healed blaze. (Rec. N.15°W.)

A Fir 30" dia., bears S.5°W., 15 lks. dist., with healed blaze. (Rec. S.12°W., 13 lks.)

BLM dependent resurvey by Daniel N. Patterson, Cadastral Surveyor under Group No. 2305, surveyed March/April 2010 (added 12/5/2019 - (DCSO records Vol. 59 Page(s) 23653)

The ¼ sec. cor. of secs. 3 & 34, on the south bdy. of the township, monumented with an iron post, 1" dia., firmly set, projecting 6" above the ground, with brass cap (properly) mkd from which the remaining original bearing tree

A fir, 38" dia., bears S.5°W., 9.9 ft., with a healed blaze.

and new bearing trees

A fir, 6" dia., bears N.89¼°W., 13.2 ft., mkd. ¼ S34 BT.

A hemlock, 7" dia., bears N.6½°W., 16.6 ft., mkd ¼ S34 BT.