

PRIMARY CORNER DESCRIPTION Cor. Secs. 26, 27, 34, & 35

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 470)  
-----  
Set post, 6" dia., 4 ft. long, in mound of stone, 18" high, 3 ft. sq. at base, for cor. to secs. 26, 27, 34, & 35, marked T20S S26 on NE, R8W S35 on SE, S34 on SW, S27 on NW face, with 1 notch on S & 2 on East edge. No witness trees.

BLM dependent resurvey by Thomas A. Tillman, under Group # 292, Surveyed June/Oct. 1950 (DCSO recs Vol. 27 Page 11340)  
-----  
Point for the cor. of secs. 26, 27, 34, & 35, proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:

T20S	R8W	
S 27	S 28	
S 34	S 35	from which

A cedar, 36" dia., bears N.70¼°E., 37 lks., mkd: T20S R8W S26 BT.  
An alder, 24" dia., bears S.31½°E., 116 lks., mkd: T20S R8W S35 BT.  
A cedar, 40" dia., bears S.69¼°E., 125 lks., mkd: T20S R8W S34 BT.  
A fir, 16" dia., bears N.36°45'W., 186 lks., mkd: T20S R8W S27 BT.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16724-5)  
-----  
The cor. of secs. 26, 27, 34, & 35, monumented with an iron post, 2" dia., firmly set, projecting 10" above the ground, with brass cap (properly) mkd.  
from which the remains of the BTs mkd. in 1950

A burned cedar snag, 47" dia., bears N.70¼°E., 37 lks., with scribe marks S26 BT visible on partially healed & burned blaze.  
A burned alder snag, 25" dia., bears S.31½°E., 116 lks., with scribe marks T20 visible on partially healed & burned blaze.  
A burned cedar snag, 40" dia., bears S.69¼°W., 125 lks., no marks remaining on burned blaze. Rescribed T20S R8W S34 BT on new blaze.  
A burned & sawed fir stump, 27" dia., bears N.39¼°W., 186 lks., with fragmentary scribe marks visible on partially healed & burned blaze.  
Set a 6 ft. steel fence post alongside the iron post. cont.

PRIMARY CORNER DESCRIPTION Cor. Secs. 26, 27, 34, & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2715, surveyed May 2013/Aug. 2014 - (DCSO records Vol. 58 Page(s) 23186)

-----  
The cor. of secs. 26, 27, 34, & 35, determined at record bearing and distance from the remains of the BTs mkd. by Tillman in 1950

A burned decayed cedar stump, 47" dia., bears N.70¼°E., 24.4 ft., with no marks visible and four wraps of logging cable.

A burned decayed cedar stump, 45" dia., bears S.69¼°W., 82.5 ft., with remains of a healed blaze.

At the corner point

Drive an aluminum rod, 21" long, 3/4" dia., 19" in a partially decayed log, with aluminum cap mkd.

T20S R8W  
S 27|S 26  
S 34|S 34  
2013

from which new reference monuments

An iron rod, 30" long, 5/8" dia., set 30" in the ground, bears N.84°55'57"E. 30.27 ft with aluminum cap mkd. RM T20S R8W 30.3 FT S26 2013 & an arrow pointing to the cor

An iron rod, 30" long, 5/8" dia., set 27" in the ground, bears N.2°27'46"W., 70.22 ft. with aluminum cap mkd. RM T20S R8W 70.2 FT S27 2013 & an arrow pointing to the cor

No suitable trees visible from cor.

Corner is located in bottom lands, in down woody debris and willow regrowth.

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2780, surveyed March/Aug. 2015 - (DCSO records Vol. 58 Page(s) 23443-5 & Plat T20-8 2016-1)

-----  
The cor. of secs. 26, 27, 34, & 35, monumented with an aluminum rod, ¾" dia., firmly set, projecting 3" above a partially decayed log, with an aluminum cap (properly) mkd. from which the remains of the BTs mkd. by Tillman in 1950

A burned decayed cedar stump, 47" dia., bears N.70¼°E., 24.4 ft. no marks visible & 4 wraps of a logging cable.

A burned decayed cedar stump, 45" dia., bears S.69¼°W., 82.5 ft., with remains of a healed blaze.

and the reference monuments set by Forkner in 2013-14

An iron rod, 5/8" dia., firmly set, with top flush with the surface of the ground, bears N.84°55'57" E., 30.27 ft., with an aluminum cap mkd. RM T20S R8W 30.3 FT S26 2013 and an arrow pointing to the cor.

continued next page

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Cor. Secs. 26, 27, 34, & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An iron rod, 5/8" dia., firmly set, projecting 3" above ground, bears N.2°27'46" W, 70.22 ft. with an aluminum cap mkd. RM T20S R8W 70.2 FT S27 2013 and an arrow pointing to the cor.

No suitable trees visible from corner.

An aluminum fence post is alongside the monument, which is located in bottom lands, in down woody debris and willow regrowth.