

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 471)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked ¼ S on W face; from which
Fir, 12" dia., bears S.42°W., 15 lks., mkd: ¼ S BT.
Fir, 10" dia., bears N.15°E., 95 lks., mkd: ¼ S BT.

BLM dependent resurvey by Thomas A. Tillman, under Group # 292, Surveyed June/Oct. 1950 (DCSO recs Vol. 27 Page 11342)

Point for the ¼ sec. cor. of secs. 26 & 27, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

¼
S 27 | S 26
1950

from which
A fir, 50" dia., bears S.5°E., 40 lks., mkd: ¼ S26 BT.
A cedar, 36" dia., bears S.80°W., 68 lks., mkd: ¼ S27 BT.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16725)

The ¼ sec. cor. of secs. 26 & 27, monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd.

from which the remains of the BTs marked in 1950
A burned & sawed fir stump, 60" dia., bears S.5°E., 40 lks., with healed blaze.
A burned cedar snag, 38" dia., bears S.80°W., 68 lks., with fragmentary scribe marks visible on burned blaze.
Set a 6 ft. steel fence post alongside the iron post.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23186-7)

The ¼ sec. cor. of secs. 26 and 27, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with a brass cap (properly) mkd.

from which the remains of the BTs mkd. by Tillman in 1950
A burned fir stump, 57" dia., bears S.5°E., 26.4 ft., with remains of a partially healed blaze.
continued next page

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A burned cedar stump, 33" dia., bears S.80°W., 44.9 ft., with scribe marks 1/ visible on burned partially healed blaze.

and new bearing trees

A fir, 19" dia., bears N.37 $\frac{3}{4}$ °E., 12.4 ft., mkd. $\frac{1}{4}$ S26 BT.

A fir, 22" dia., bears N.78 $\frac{1}{2}$ °W., 19.1 ft., mkd. $\frac{1}{4}$ S27 BT.

Drive a steel fence post, found disturbed, alongside the cor.