

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 472)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked 1/4 S on W face; from which
Alder, 6" dia., bears N.55°E., 42 lks., mkd: 1/4 S BT.
Alder, 8" dia., bears S.42°W., 90 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Thomas A. Tillman, under Group # 292, Surveyed June/Oct. 1950 (DCSO recs Vol. 27 Page 11344)

Point for the 1/4 sec. cor. of secs. 22 & 23, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:

1/4
S 22 | S 23
1950

from which

A fir, 40" dia., bears N.14°E., 88 lks., mkd: 1/4 S23 BT.

A fir, 50" dia., bears S.66°W., 57 lks., mkd: 1/4 S22 BT.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16726-7)

The 1/4 sec. cor. of secs. 22 & 23, monumented with an iron post, firmly set, projecting 6" above ground, with brass cap (properly) mkd.

from which the remains of the BTs marked in 1950

A burned & sawed fir stump, 56" dia., bears S.66°W., 57 lks., no marks remaining on burned blaze.

and a new BT

A burned cedar, 10" dia., bears S.86°E., 27 lks., mkd: 1/4 S23 BT.

Set a 6 ft. steel fence post alongside the iron post.

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #2000, surveyed Jan./March 2005 - (DCSO rec. Vol. 55 Page(s) 21758-9)

The 1/4 sec. cor. of secs. 22 and 23, monumented with an iron post, 1" dia., firmly set, projecting 8" above the ground, with brass cap (properly) mkd.

from which the remains of a BT mkd. by Tillman in 1950

A decayed fir stump, 50" dia., bears S.66°W., 37.6 ft., with scribe marks 1/4 S22 BT visible on open blaze.

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias	Description
Alias	Description
Alias	Description
Alias	Description

and the remains of a BT mkd. by Glenn, et al., in 1967
A root hole with cedar log alongside, 8" dia., bears S.86°E., 17.8 ft., no marks visible.
and new bearing trees
A fir, 13" dia., bears S.48°E., 7.7 ft., mkd. ¼ S23 BT.
A fir, 9" dia., bears S.20°W., 19.0 ft., mkd. ¼ S22 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

Ron Rice, NW Land Surveying - March 2013 - C.S. File 65/78-36

Found - 1950 GLO brass cap with the following accessories:
A decayed fir stump, 50" dia., bears S.66°W., 37.6 ft., with scribe visible marks ¼ S22 BT on open blaze. (Fd Same)
A root hole with cedar log alongside, 8" dia., bears S.86°E., 17.8 ft., no marks visible. (Found same)
A fir, 13" dia., bears S.48°E., 7.7 ft., mkd. ¼ S23 BT. (Now 15", healed face)
A fir, 9" dia., bears S.20°W., 19.0 ft., mkd. ¼ S22 BT. (Now 15", healed face)
New - 11" D.Fir bears N.24°W., 19.5 ft. - blazed, scribed ¼ S22 BT
7" D.Fir bears N.6°E., 6.6 ft. - blazed, scribed ¼ S23 BT
Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags.
Compass Declination 16° East