

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

	<p>17" Fir snag, N.45°W., 12.0' (scar vis.) Rec. N.43¼°W., 11.2' (1954 BT) 12" Fir snag, S.75°E., 33.3' (scar vis.) Rec. S.76°E., 33.0' (1967 BT) 20" Fir snag, N.34°E., 17.5' (scar vis.) Rec. N.34½°E., 17.2' (1967 BT) New BTs- 6" Fir, S.2°W., 23.3', scribed/painted red. 7" Fir, N.73°W., 22.0', scribed/painted red. Note - Corner lies on South slope about 150' east of ridge. Ridge bears N.70°E., & S.70°W.</p>
	<p>Ron Rice - March 1, 2013 - C.S. File 65/78-17 ----- Found - 1954 GLO brass cap with the following accessories: 15" D.Fir snag bears S.57°W., 35.0 ft. - healed face 17" D.Fir snag bears N.45°W., 12.0 ft. - healed face Record 12" D.Fir snag N.34°E., 17.5 ft. - not found 20" D.Fir snag bears N.34°E., 17.5 ft. - healed face 10" D.Fir bears S.2°W., 23.3 ft. - healed face 17" D.Fir bears N.73°W., 22.0 ft. - healed face New - 14" D.Fir bears N.19°W., 29.5 ft. - blazed, scribed, ¼ S11 BT 14" D.Fir bears S.57°W., 10.1 ft. - blazed, scribed, ¼ S14 BT. Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags. Declination 16° East</p>