

PRIMARY CORNER DESCRIPTION Cor. Secs. 23, 24, 25, & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Page(s) 466)

Set post, 6" dia., 4 ft. long, in mound of rock, 18" high, 3 ft. sqr. at base, for cor. to secs. 23, 24, 25, & 26, marked T20S S24 on NE., R8W S25 on SE., S26 on SW., S23 on NW face, with 1 notch on E & 2 on S edges. No witness trees.

BLM dependent resurvey by Thomas A. Tillman, Group # 292, Surveyed June/Oct. 1950 (DCSO records Vol. 27 Page(s) 11338)

The cor. of secs. 23, 24, 25, & 26, monumented with a badly decayed cedar stake, 4 ft. long, 3" sq., with the scribe mark S and other partial scribe marks visible on one face, lying in a small mound of stone.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:

T20S	R8W
<u>S 23</u>	<u>S 24</u>
S 26	S 25
1950	

from which

A cedar, 48" dia., bears N.15½°E., 75 lks., mkd: T20S R8W S24 BT.

A hemlock, 48" dia., bears S.26°E., 113 lks., mkd: T20S R8W S25 BT.

A hemlock, 34" dia., bears S.36½°W., 51 lks., mkd: T20S R8W S26 BT.

A cedar, 70" dia., bears N.67½°W., 58 lks., mkd: T20S R8W S23 BT.

Reset the cedar stake alongside the iron post.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16719-20)

The cor. of secs. 23, 24, 25, & 26, monumented with an iron post, 2" dia., firmly set, projecting 6" above ground, with brass cap (properly) marked, from which the remains of the BTs marked in 1950

A burned cedar snag, 48" dia., bears N.15½°E., 75 lks., with scribe marks S R8W S24 T visible on partially healed & burned blaze.

A burned hemlock snag, 55" dia., bears S.26°W., 113 lks., with scribe marks T20S R8W S25 BT visible on open & burned blaze.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 23, 24, 25, & 26

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A burned hemlock snag, 37" dia., bears S.36½°W., 51 lks., with scribe marks T20S R8W S26 BT visible on open & burned blaze.

A burned cedar snag, 70" dia., bears N.67½°W., 58 lks., with scribe marks T20S R8W S23 BT visible on open & burned blaze.

Set a 6 ft. steel fence post alongside the iron post.

Ronald L. Rice, Ward NW Inc. - Jason Collier - Feb. 13, 2012 - C.S. File 65/76-17 & M167-69 (3/2014)

Found - BLM brass cap, 1950 with the following accessories:
70" Rotted R. Cedar stump bears N.67½°W., 38.3'
55" Rotted Hemlock stump bears S.26°W., 74.6'
48" Rotted R. Cedar stump bears N.15½°E., 49.5'
37" Rotted Hemlock stump bears S.36½°W., 33.7'

New - 18" D.Fir bears N.32°W., 25.4' - blazed, scribed "T20S R8W S23 BT"
17" D.Fir bears S.36°W., 15.8' - blazed, scribed "T20S R8W S26 BT"
14" D.Fir bears S.55°E., 9.3' - blazed, scribed "T20S R8W S25 BT"
12" D.Fir bears N.51°E., 24.4'- blazed, scribed "T20S R8W S24 BT"

Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags.
Compass Declination 16° East

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23182-3)

The cor. of secs. 23, 24, 25, & 26, perpetuated by Rice, in 2012; monumented with an iron post, 2" dia., firmly set, projecting 6" above ground, with a brass cap (properly) mkd. from which the remains of the BTs mkd. by Tillman in 1950

A decayed hemlock stump, 47" dia., bears S.26°E., 74.6 ft., no marks visible.

A decayed hemlock stump, 22" dia., bears S.36½°W., 33.7 ft., no marks visible.

A decayed cedar stump, size indeterminate, bears N.67½°W., 38.3 ft., no marks visible.

and the bearing trees mkd. by Rice

A fir, 13" dia., bears N.51¼°E., 24.4 ft., with scribe marks T20S R8W S24 BT visible on pitchy partially healed blaze and a nail at the base on the right side center. continued next page

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Cor. Secs. 23, 24, 25, & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 15" dia., bears S.54½°E., 9.3 ft., with illegible scribe marks visible on partially healed blaze and a nail at the base on the left side center.

A fir, 18" dia., bears S.36°W., 15.8 ft., with scribe marks T20S R8W S2 and other illegible scribe marks visible on pitchy partially healed blaze and a nail at the base on the right side center.

A fir, 18" dia., bears N.30½°W., 25.4 ft., with scribe marks 20S R8W S23 BT visible on pitchy partially healed blaze and a nail at the base on the right side center.

A steel and an aluminum fence post are alongside the cor.
From the corner
N., 25 ft., drainage, 3 ft. wide, course S.55°W.