

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A decayed hemlock stump, 40" dia., bears N.36°W., 39.6 ft., no marks visible.
and new bearing trees
A fir, 13" dia., bears S.44³/₄°E., 16.1 ft., mkd. ¹/₄ S25 BT.
A fir, 9" dia., bears N.71³/₄°W., 8.6 ft., mkd. ¹/₄ S24 BT.
Each new bearing tree has a 2¹/₂"x ¹/₄" magnetic nail (Mag Nail) driven at the base right side-center.

Ronald L. Rice, Ward NW Inc. - Jason Collier - Feb. 13, 2012
- C.S. File 65/76-18

Found - BLM brass cap, 1950, w/the following accessories:
16" D.Fir bears S.44³/₄°E., 16.1' - healed face
10" D.Fir bears N.71³/₄°W., 8.6' - healed face
40" Rotted Hemlock stump bears N.36°W., 39.6' - rotted face
22" Hemlock snag bears S.9°W., 17.2' - no marks visible
New - 14" D.Fir bears S.46°W., 38.9' - blazed, scribed "¹/₄ S25 BT"
12" D.Fir bears N.90°E., 15.6' - blazed, scribed "¹/₄ S24 BT"
Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags.
Compass Declination 16° East