TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 18; & 13, T20-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Pages 202-03)

Set a post 4 ft. long, 4" sq., 18" in the ground for ¼ sec. cor. marked ¼ S on W. face; from which

A Fir 36" dia., bears S.8°E., 67 lks. dist., mkd. ¼ S BT.
A Fir 18" dia., bears N.22°W., 40 lks. dist. mkd. ¼ S BT

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #297, Surveyed May 1951/Oct. 1952 - (DCSO records Vol. 27 Page(s) 11677)

The ¼ sec. cor., monumented with the decayed remains of a wooden post, from which the original bearing trees:

A Fir 48" dia., bears S.13°E., 73 lks. dist. mkd. ¼ S BT on the bark. (Rec. desc. S.8°E., 67 lks.)
A Fir 56" dia., bears N.25°45'W., 45 lks. dist. mkd. ¼ S BT on badly scaled old bark blaze. (Rec. desc., N.22°W., 40 lks.)

At the corner point
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd:

¼
S 13|S 18
1952

from which a new bearing tree

An Alder 12" dia., bears N.43°W., 17½ lks. dist. mkd. ¼ S13 BT.

Deposit the point and other remains of the old post at the base of the iron post.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23083)

The ¼ sec. cor. of secs. 13 & 18, monumented with an iron post, 1" dia., firmly set, with top 6" below the surface of the ground, with brass cap (properly) mkd.
from which the remains of the original bearing trees

A decayed fir stump, 33" dia., bears S.13°E., 48.2 ft., no marks visible.
A burned and decayed fir stump, 40" dia., bears N.25¾°W., 29.7 ft., no marks visible.

and new bearing trees

A fir, 10" dia., bears S.1°E., 26.6 ft., mkd. ¼ S 18 BT.
A fir, 10" dia., bears N.35°W., 19.5 ft., mkd. ¼ S13 BT.