

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 6, T21-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Wm. Thiel under Contract #260 dated April 17, 1877 - (DCSO records Vol. 1 Page(s) 303)

 Set Maple post for 1/4 sec. cor. between secs. 31 and 6; from which an

- Ash 14" dia., bears S.75°W., 44 lks. dist.
- An Alder 15" dia., bears N.34°E., 59 lks. dist.

June 6

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 1 Page(s) 364-65)

 Point for 1/4 sec. cor. All traces of it had been destroyed by floods.

I set Alder post 5 ft. long, 4" sq., 24" in the ground 15" North of the right bank of Smiths River; post marked 1/4 S on the N. face; from which

- An Alder 8" dia., bears N.3°30'W., 63 lks. dist. mkd. 1/4 S BT.
- An Alder 10" dia., S.82°W., 20 lks. dist. mkd. 1/4 S BT.

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12446)

 Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, to solid rock, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:

1/4 $\frac{S \ 31}{S \ 6}$
 1953

from which

- An Iron post 3 ft. long, 1" dia., set 32" in the ground, for a reference monument, in fence row at S. side of Smith River Road, bears North, 308 lks. dist., mkd. 1/4 S31 RM 1953 and an arrow pointing to the corner.
 - An unmarked iron pipe, 1 1/2" dia., projecting 10" from a drill hole in solid rock, bears N.82°58'E., 5.33 chs. dist.
 - An Alder 12" dia., bears N.86 1/4°E., 174 lks. dist. mkd. 1/4 S31 BT.
 - A Cedar 25" dia., S.86 1/4°W., 139 lks. dist. mkd. 1/4 S6 BT.
- The 1/4 cor. is located 28 lks. N. of the right bank of Smith River.

(Cont. Next Page)

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 140100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 6, T21-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - John M. Powell, and crew -
Sept. 1969 - C.S. File 53/66-20

Found - GLO brass cap, properly mkd. in 1953. Brass cap in
fence row, North 203.3 ft.
1½" Iron pipe in bedrock, bears N.86°E., 351.8 ft.
25" Cedar now 36", S.86°W., 91.7 ft.
No trace of NE. BT.
New BT - 19" Cedar N.73°E., 255.2 ft. mkd. ¼ S31 CS BT.
Reblazed and rescribed:
36" Cedar S.86°W., 91.7 ft. "¼ S6 CS BT"

Fd. OK, Feb. 1992 by Robt. Ward - M 114-48
Fd. OK, Feb. 1993 by R. Ward - M 116-61