

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel under contract 260 dated Apr. 17, 1877- (DCSO records Vol. 1 Page(s) 328)

-----  
Set a post, 4 ft. long, 4" sq. 24" in the ground, for cor. to secs. 19, 20, 29, & 30, marked T20S S20 on NE, R9W S29 on SE, S30 on SW, S19 on NW faces, with 2 notch on S & 5 notches on E edges; from which

A fir, 30" dia., bears N.27°E., 39 lks., mkd: T20S R9W S20 BT.

A fir, 40" dia., bears S.51°W., 75 lks., mkd: T20S R9W S30 BT.

A fir, 30" dia., bears S.21°E., 193 lks., mkd: T20S R9W S29 BT.

A fir, 48" dia., bears N.52°W., 34 lks., mkd: T20S R9W S19 BT.

BLM dependent resurvey by Thomas A. Tillman & Joseph S Gawron, under Group # 306, Surveyed May 1953 - Oct. 1954 (DCSO recs Vol. 29 Page(s) 12520-1)

-----  
The cor. of secs. 19, 20, 29, & 30, perpetuated with an iron pipe, 4 ft. long, 2" dia., driven 12" in the ground, with iron pipe marked

19 20  
T 20 S R 9 W  
30 29

from which the remaining orig. BTs

A fir stump, 40" dia., bears N.27°E., 39 lks., marked BT on bark blaze, most of which is broken off & decayed.

A fir, 60" dia., bears S.49°W., 75 lks., with nearly illegible scribe marks on bark blaze. (Rec. bearing S.51°W.)

A fir, 60" dia., bears N.52°W., 34 lks., marked T20S R9W S19 on bark blaze.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked:

T20S R9W  
S 19 | S 20  
S 30 | S 29  
1953

from which new BTs

A hemlock, 12" dia., bears N.5°E., 94 lks., mkd: T20S R9W S20 BT.

A hemlock, 8" dia., bears S.55½°E., 17 lks., mkd: T20S R9W S29 BT.

continued next page

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Cor. Secs. 19, 20, 29, & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. & used on BLM dependent resurvey by Harvey E. Wofford, Cadastral Surveyor under Group #1090, surveyed April/May 1982 - (DCSO records Vol. 45 Page(s) 17460)

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23109-10)

-----  
The cor. of secs. 19, 20, 29, and 30, monumented with an iron post, 2" dia, firmly set, projecting 10" above ground, with brass cap (properly mkd.

from which the remains of the original bearing trees

A decayed fir stump, size indeterminate, bears N.27°E., 25.7 ft., no marks visible.

A fir stump, 70" dia., bears S.49°W., 49.5 ft., no marks visible.

A fir, 75" dia., bears N.52°W., 25.7 ft., with scribe marks T20 R9W and other illegible scribe marks visible on bark blaze. (Record, 22.4 ft.)

and a bearing tree mkd. by Tillman and Gawron in 1953-54

A hemlock, 23" dia, bears S.55½°E., 11.2 ft., with a healed blaze.

and new bearing trees

A maple, 16" dia, bears N.78°E., 49.7 ft., mkd. T20S R9W S20 BT.

A cedar, 19" dia, bears S.33°W., 30.2 ft., mkd. T20S R9W S30 BT.