

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated April 8, 1920, Group 56 - (DCSO records Vol. 1 Page(s) 400-1)

-----  
Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor., with brass cap marked:

1/4  
S 7 | S 8  
1921

from which

- A fir, 40" dia., bears S.55°E., 23 lks., mkd: 1/4 S8 BT.
- A maple, 28" dia., bears S.28°W., 25 lks., mkd: 1/4 S7 BT.

Douglas Co. Surveyors Office - L.E. Monrean - R.B. Kimberling - 5/10/1977 - C.S. File 59/34-12

-----  
Found - 1921 GLO brass cap rusted & broken off at the ground  
A 40" D.Fir, bears S.57 1/2°E., 15.2 ft. Tree has well healed single blaze. We do not open.  
A 28" Maple bears S.28°W., 16.5 ft. Tree has well healed blaze. We do not open.

Set - 1"x30" IP at 1/4 cor., 26" into the ground. Attached brass cap is marked "Douglas County Surveyor"

T20S R9W  
1/4 S7 S8  
1977

New BT - A 33" Maple bears S.57 1/2°W., 69.3 ft. Tree double blazed & scribed "1/4 S7 CS BT"